

Additional Funding Request

INVOICE

DE001	CSS# 31328 WO# 14522 Asset# NA			
Description of Repairs	Found unit not funding and low on refrigerant. Added R410a to system and checked for leaks. No leaks found but could not access other office. System blowing 63 degree discharge air no other problems found.			
Diagnosis: Initial Work Order	The AC in the OMS offices is not working.			
Diagnostic Fee	\$ 0			
Additional Labor Cost to Perform Repairs	\$ 600 SS \$100/hr x 6			
Additional Cost	\$ 68.22			
	Refrigerant	1	\$68.22	\$68.22
Total Cost of Repair	\$ 668.22			

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: DE 0001

Date of Visit: 7/1/2021

Contractor Personnel on Site:

1. Brian Davis

4. _____

2. _____

5. _____

3. _____

6. _____

Service Calls - Service Call Number and Description

1. OMS office A/C hot - Added 24104

2. _____

3. _____

WO # 14522

CSST # 31238

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Brian Davis

Date: 7/1/2021

Signed: Brian Davis

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline.

Print Name/Rank: JASON GARN AFOS

Date: 7/1/21

Signed: Jason Garn

E-Mail: _____



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

PLEASE PAY BY

07/31/2021

AMOUNT

\$668.22

INVOICE DATE

07/01/2021

INVOICE NO. 82817

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Job Name: 14522
Site: DE001 North New Street
Site Address: 344 North New Street
Dover DE 19904

Description

WO#: 14522

CSS Ticket Number: 31238

Problem: The AC in the OMS offices is not working.

Brian Davis 07/01/2021 Work Note

Found unit not funding and low on refrigerant. Added R410a to system and checked for leaks and couldn't find any leaks but we could not access other office. System blowing 63° discharge air no other problems found. Work complete.

9208 - Service

Item	Quantity	Unit Price	Total
Refrigerant	1.00	\$68.22	\$68.22
HVAC Labor Rate	6.00 hrs	\$100.00	\$600.00
Labor			\$600.00
Materials			\$68.22
Sub-Total ex Tax			\$668.22

Make all checks payable to S&S Mechanical. Overdue accounts are subject to a service charge of 1.5% per month. Thank you for your business.

Sub-Total ex Tax	\$668.22
Tax	\$0.00
Total inc Tax	\$668.22
Amount Applied	\$0.00
Balance Due	\$668.22

-S&S Mechanical also accepts all major credit cards. Call 301-574-1555 to pay an invoice via credit card-

BLESSURES ET MEME ENTRAINER
LA MORT. COUPER LES SOURCES
D'ALIMENTATION A DISTANCE
AVANT LE DEPANNAGE.

FUJITSU

SPLIT TYPE AIR CONDITIONER
OUTDOOR USE

MODEL No. AOU18RLXFZ
SERIAL No. LTN 021536

AHRI

CERTIFIED

www.ahrirectory.org

Unitary Small HP
AHRI Standard 210/240

Qualification applies only when the complete system is listed with AHRI.

SOURCE 208/230-V 60Hz 1-PH

		COOL	HEAT
TOTAL	AMPS.	10.0/10.0	10.0/10.0
OUTDOOR COMPRESSOR	AMPS.	8.5/8.5	8.5/8.5
FAN MOTOR	AMPS.	0.5/0.5	0.5/0.5

MINIMUM CIRCUIT AMPACITY 12.1 A

MAX. CKT. BKR. 15 A

COMPRESSOR LOCKED-ROTOR AMPERES 24 A

REFRIGERANT R410A FACTORY CHARGED 4 lb 14 oz

DESIGN PRESSURE HIGH SIDE 450 psi
LOW SIDE 240 psi



Intertek

91987
ETL LISTED
CONFORMS TO
UL STD. 1995
CERTIFIED TO
CAN/CSA STD.
C22.2 NO. 250

APPLICABLE INDOOR UNIT:

ASU7RLF	ASU9RLF	ASU12RLF	
ASU9RLS2	ASU12RLS2	ASU7RLF1	ASU9RLF1 ASU12RLF1
AUU7RLF	AUU9RLF	AUU12RLF	
ARU7RLF	ARU9RLF	ARU12RLF	AGU9RLF AGU12RLF

Halcyon HFI Compatible

FUJITSU GENERAL LIMITED

MADE IN THAILAND