

Additional Funding Request

DE007	CSS# 31393 WO# 14532				
Description of Repairs	S&S proposes to remove and replace the condenser motor on the York Chiller.				
Diagnosis: Initial Work Order	Unusual noise coming from the chiller.				
Diagnostic Fee	\$ 250 Labor \$100/hr x 2.5				
Additional Labor Cost to Perform Repairs	\$ 1,000 Labor \$100/hr x 10				
Additional Material Cost to Perform Repairs	\$ 1244.01 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Fan Motor (plus shipping)</td> <td style="width: 10%;">1</td> <td style="width: 20%;">1244.01</td> <td style="width: 30%;">1244.01</td> </tr> </table>	Fan Motor (plus shipping)	1	1244.01	1244.01
Fan Motor (plus shipping)	1	1244.01	1244.01		
Total Cost of Repair	\$ 2494.01				



S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 665

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 14532
Quote No: 665
Site: DE007 Olgetown Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 07/16/2021
Valid For: 30 Day(s)

WO 14532

CSS Ticket Number: 31393

Problem: At DE007 John investigated. After his investigation it was found that we need to replace the condenser motor on the chiller. Is this something that you will have to go out and investigate, or is this something that you can provide a quote for without investigation?

S&S proposes to remove and replace the condenser motor on the York chiller.
S&S will then complete a system check to ensure everything is running properly.

Service

Item	Quantity	Unit Price	Total
Fan Motor, Low Noise, 2 HP, 850 rpm	1.00	\$1,144.01	\$1,144.01
Shipping	1.00	\$100.00	\$100.00
Diagnosis Fee	1	\$250.00	\$250.00
HVAC Labor Rate	10	\$100.00	\$1,000.00
		Sub-Total ex Tax	\$2,494.01
		Tax	\$0.00
		Total inc Tax	\$2,494.01
		Labor	\$1,250.00
		Materials	\$1,244.01
		Sub-Total ex Tax	\$2,494.01
		Tax	\$0.00
		Total inc Tax	\$2,494.01

HVAC & Refrigeration Parts

YORK

Fan Motor, Low Noise, 2 HP, 850 rpm

Item # 42FL09

Mfr. Model # 024-34980-102

UNSPSC # 0

Catalog Page # N/A

Country of Origin Mexico. Country of Origin is subject to change.



Tap image to zoom.

Web Price

\$953.34 / each

Qty

1

Add to Cart




Shipping



Pickup

Ships from supplier. Expected to arrive on or before
Wed. Aug 04.



...SERIAL
SERIAL

460 RE
34980-001
Y-12

024-3-2
HP 00820
KCI
OH 3

69019
RPM 3.4|3.7
FR 115
56Y
66 C

3
ENCL E CONT.

DUY

AON P56C64A50 MEXICO

MODEL Assembled in Mexico

卷之三

Digitized by srujanika@gmail.com

THE JOURNAL OF CLIMATE

1000 1000

卷之三

卷之三