

Additional Funding Request

VA048	CSS# 31425 WO# 14534							
Description of Repairs	Parts and labor to remove ductless air handler unit in the motor pool office to re-secure the mounting bracket, remount the ductless air handler unit, remove and replace the condensate pump and make all necessary connections as well as start and check for proper operation.							
Diagnosis: Initial Work Order	02 A/C unit wall mounted in Motor pool office --Will found the unit pulling away from the wall and the condensate pump needs to be replaced also.							
Diagnostic Fee	<p>\$ 118</p> <p>Labor \$118/hr x 1</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 936</p> <p>Labor \$109.50/hr x 8</p>							
Additional Material Cost to Perform Repairs	<p>\$ 216.03</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Condensate Pump</td> <td style="width: 10%;">1</td> <td style="width: 15%;">216.03</td> <td style="width: 15%;">216.03</td> </tr> </table>				Condensate Pump	1	216.03	216.03
Condensate Pump	1	216.03	216.03					
Total Cost of Repair	<p>\$1020.03</p> <p>Note: (\$250) CM Credit Applied</p>							



Phone: 804-219-3742
Email: greg.giannasi@colonialwebb.com

QUOTE DETAILS

Quote Creator: Greg Giannasi
Original WO #: 724018
Technician: Matthew Taylor
Customer: Tidewater Inc
Contact: Mary Lowery
Phone #: 410-967-5346
Fax #:
Email: mary.lowery@tideh2o.net

Regular Service Quote # 201-21-0731

Date: July 9, 2021

Site/ Store # :

Site Name: 1st Lieutenant Jimmie Montieth A

Location: 1741 East Belt Boulevard
Richmond, VA 23224

URGENCY- Immediate Repair

Repair is needed to limit loss of product, further damage to equipment, catastrophic failure and/or emergency comfort heating/cooling. Equipment down.

The following is recommended by Matthew Taylor, your building solutions provider.

Equipment Type/System: _____ Area Served: _____ Unit #: _____
Manufacturer: _____ Model #: _____ Serial #: _____
Repairs Found : _____ Tonnage _____ # of Stages: _____
Stages Down: _____ Year Made: _____ Age: _____

Diagnosis

During a recent service call, our technician found that the condensate pump on the ductless air handler unit in the motor pool office has failed. Technician also found that the air handler mounting bracket is loose. Technician recommends replacing the condensate pump and resecuring the mounting bracket. If repairs are not made, the air handler unit could leak condensate and cause damage to the space.

Solution

Technician will remove ductless air handler unit in the motor pool office to re-secure the mounting bracket. Will remount the ductless air handler unit. Technician will remove and replace the condensate pump and make all necessary connections. Will start and check for proper operation. Lead time for equipment/parts/materials is 5-7 business days after receipt of order (ARO). All work is to be performed during normal working hours. Anything unforeseen or found not in the above mentioned scope will be brought to your attention and quoted for approval.

Description	Hours	Totals	Vehicle & Fuel Charge
TECHNICIAN	4.00	\$ 472.00	\$ 60.00
HELPER	4.00	\$ 404.00	\$ -
INITIAL SERVICE CALL	1.00	\$ 118.00	
SUPERVISOR/QC	-	\$ -	
	-	\$ -	
TOTAL HOURS	9.00	\$ 994.00	Total Labor Price

This proposal contains the cost for your initial service call. If you elect not to proceed with the recommended repair you will only be invoiced for the initial work performed at your agreed upon rates.

General Provisions:

1. Proposal includes only those parts, materials, and services specifically noted. If, during the course of our work, other conditions are discovered that require further repairs or diagnostic services, those will be reported and authorization secured for the additional work. The additional work will be beyond the scope of this proposal and will be billed on a time and material basis at prevailing rates.
2. This quote shall be void after 15 days unless validated in writing by ColonialWebb Contractors.
3. Acceptance of this proposal, either by signature, purchase order or letter of authorization shall be construed to mean acceptance of the proposal in its entirety unless otherwise noted.
4. Standard payment terms are net 30 days.
5. In the event that payment is not made in accordance with the terms stated herein, the purchaser agrees to pay reasonable legal fees associated with the collection of such payments, and shall, in addition, pay interest at a rate of 1.5% per month on any past due amounts.
6. Parts, materials, and labor are warranted for a period of 30 days from the date of installation. Labor for Compressors are warranted for a period of 90 days. Compressor is warranted per manufacturer's warranty.
7. This proposal may contain recommendations of products or services to lessen the risk of spreading infectious disease through HVAC Systems. At this time, no products or service can guarantee or substantiate claims to eradicate the SARS-CoV-2 virus or the disease COVID-19. Our recommendations are based on the understanding of infectious disease control in general and, more specifically, the ASHRAE Position Document on Infectious Aerosols dated April 14, 2020. ColonialWebb hereby disclaims any and all warranties of any kind, whether express, implied, or statutory, as to the efficacy of such products or services to reduce the risk of spread of infectious disease

Pandemic:

As you are aware, the world is experiencing a pandemic as it relates to the coronavirus ("Coronavirus"). This health emergency has the potential of impacting multiple facets for this proposed work including, but not limited to: labor, personnel, manufacturing, equipment, materials, transportation, and related supply chains, which have the potential to adversely impact the timeline of the repair. These potential, unusual and unavoidable, delays, which are outside of the control of ColonialWebb contractors and cannot be anticipated, have been specifically excluded from this proposal.

Approval: _____ Date: _____

Thank you for choosing ColonialWebb as your solutions provider!

 * A C K N O W L E D G E M E N T - Quote Order *

CLAY AIRECO SUPPLY, INC.
 3100 W. CLAY STREET
 RICHMOND VA 23230 (804)359-2468/

CUST#: 3915 SHIP TO: Order Date: 07/09/21 Whse: 026 ORDER#: 8672659-00

Placed By Taken By Salesrep Out
 ANHA CHDU

BILL TO: (804)916-1400 FAX#: 8042626298 SHIP TO:
 COLONIALWEBB -RICHMOND-
 ACCOUNTS PAYABLE
 2820 ACKLEY AVENUE
 RICHMOND, VA 23228
 COLONIALWEBB -RICHMOND-
 ACCOUNTS PAYABLE
 2820 ACKLEY AVENUE
 RICHMOND, VA 23228

Customer PO: CONDENSATE PUMP Special Instructions: IN STOCK

Ship Via: PICK-UP Request Date: 07/10/21 Ship Date: Terms: 1% 10thprox

Line #	Product And Description	Quantity Ordered	Quantity B.O.	Quantity Shipped	Qty Um	Unit Price	Net Price
1	X85-003 MICRO BLUE CONDENSATION PUMP 110V/230V W/RESVR S	1			ea	150.26900 *	150.27
1 Lines Total						Total	150.27
						Taxes	9.02
						Invoice Total	159.29
						** NOT AN INVOICE OR RECEIPT **	

** This Quote Will Be Canceled On: 08/10/21 **
 THANK YOU FOR YOUR BUSINESS!





