

Additional Funding Request

VA049	CSS# 31445 WO# 14536							
Description of Repairs	Labor and materials to replace motors in fan coil units, assets 3Y127, 3Y128, 3Y129, 3Y130.							
Diagnosis: Initial Work Order	The motors need to be replaced in Fan coil units Asset's 3Y127 , 3Y128 , 3Y129 , 3Y130 . PM Credit \$250 for each asset will be applied							
Diagnostic Fee	\$ 240 Labor \$80/hr x 3							
Additional Labor Cost to Perform Repairs	\$ 640 Labor \$80/hr x 8							
Additional Material Cost to Perform Repairs	\$ 1,204.96 <table border="1"><tr><td>2827P 1/10HP 115V DS PSC 1050R 4.8 AMPS</td><td>4</td><td>301.24</td><td>1,204.96</td></tr></table>				2827P 1/10HP 115V DS PSC 1050R 4.8 AMPS	4	301.24	1,204.96
2827P 1/10HP 115V DS PSC 1050R 4.8 AMPS	4	301.24	1,204.96					
Total Cost of Repair	\$ 1,084.96 (\$250) CM credit applied x4							



WORK ESTIMATE

CSS #: 31445

Work Order #: 14536

Emergency ☐

Urgent ☐

Routine ☒

Company Name:	Tidewater, Inc.	Facility ID:	NY051
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Will Schultz		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace motors in fan coil units, assets 3Y127, 3Y128, 3Y129, 3Y130.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			3	\$240.00
(\$250.00) CM Credit	4	(\$250.00)		(\$1,000.00)
2827P 1/10HP 115V DS PSC 1050R 4.8 AMPS	4	\$301.24		\$1,204.96
Labor			8	\$640.00
SUB-TOTAL COSTS:		Materials Total	\$1,204.96	Labor \$880.00
TOTAL			\$1,084.96	

Page #: 1

Time: 14:09

* A C K N O W L E D G E M E N T - Quote Order *

CLAY AIRECO SUPPLY, INC.
3100 W. CLAY STREET
RICHMOND

VA 23230

(804)359-2468/

CUST#: 29480 SHIP TO:

Order Date: 07/23/21

Whse: 026

ORDER#: 8700595-00

Placed By

Taken By Salesrep Out
DAMC 99

BILL TO: (410)540-8700 FAX#: 410-579-1685
TIDEWATER, INC.
6625 SELNICK DR.

SHIP TO:
TIDEWATER, INC.
6625 SELNICK DR.

ELKRIDGE, MD 21075

ELKRIDGE, MD 21075

Customer PO:

Special Instructions:

Ship Via: PICK-UP

Request Date: 07/24/21

Ship Date:

Terms: ** COD **

Line #	Product And Description	Quantity Ordered	Quantity B.O.	Quantity Shipped	Qty Um	Unit Price	Net Price
1	2827P 1/10HP 115V DS PSC 1050R 4.8 AMPS	4			ea	239.08500 *	956.34

1 Lines Total

Total 956.34
Taxes 57.38
Invoice Total 1013.72
** NOT AN INVOICE OR RECEIPT **

THANK YOU FOR YOUR BUSINESS!

Dayton**Room A/C Motor**MOD
NO **4M038B**

HP 1/10 RPM 1000 / 5 Spd FR 42Y2 LR39894
VOLTS 115 AMPS 4.8 PH 1
HZ 60 ENCL OPAO INS CL B E47479
Thermally Protected 40° C Amb Air Over Cont

MTR REF: F4B-0XPHJ-2677

MFG NO G98 3

Common C White

High 1 Black

Med Hi 2 Yellow

Med 3 Blue

Med Lo 4 Orange

Low 5 Red

Reoil Brgs: SAE 20 Oil

Continuous Duty: Every Yr.

Intermittent Duty: Every 2 Yrs

Occasional Duty: Every 5 Yrs

Mfg. for Dayton Electric Mfg. Co., Niles, IL 60714 USA

UNIVERSAL ELECTRIC CO. INC.
SER. 1138 88758 800 DANGER 1234
R.O.A. & CO. INC. 87. 1138 800 1234
SPECIALLY PROTECTED 1

UNIVERSAL ELECTRIC CO. INC. MADE IN U.S.A.
SER 112A 56755K MOD 0A3E12448 LG 1245
S1A A #C40 S.P. 115V 60HZ 1.4A 1050000
PERMANENT PROTECTED 1

ALTERNATOR, ELECTRIC CO. 100
110V. 1500 RPM. 1500 RPM. 1500 RPM.
1500 RPM. 1500 RPM. 1500 RPM.
1500 RPM. 1500 RPM. 1500 RPM.

