

Additional Funding Request

DE007	CSS# 31501 WO# 14540				
Description of Repairs	Labor and materials to replace 2 pressure relief switches.				
Diagnosis: Initial Work Order	ITEM#2-Water Heaters-WH1 &WH2 Need safety valves replaced				
Diagnostic Fee	\$ 160 Labor \$80/hr x 2				
Additional Labor Cost to Perform Repairs	\$ 400 Labor \$80/hr x 5				
Additional Material Cost to Perform Repairs	\$ 588.40 <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Pressure Relief Switches</td> <td>2</td> <td>294.20</td> <td>588.40</td> </tr> </table>	Pressure Relief Switches	2	294.20	588.40
Pressure Relief Switches	2	294.20	588.40		
Total Cost of Repair	\$ 1228.40				

WORK ESTIMATE

 CSS #:

 Work Order #:

 Emergency

 Urgent

 Routine

 X

Company Name:	Tidewater, Inc.		Facility ID:	DE007	
Contractor POC:	Adam Cology				
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)		
E-Mail Address:	adam.cology@tideh2o.net				
Assigned Technician(s):	John Brown				

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace 2 pressure relief switches.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			3	\$240.00
Temp and Pressure Relief Valve	2	\$294.20		\$588.40
Labor			5	\$400.00
SUB-TOTAL COSTS:		Materials Total	\$588.40	Labor \$640.00
			TOTAL	\$1228.40



WATTS

Temperature and Pressure Relief Valve, 3,085,000 BtuH, 150 psi, 6 in Thermostat Length

Item # 26X149

Mfr. Model # 1 LF140X6 150/210

UNSPSC # 40141606

Catalog Page # N/A

Country of Origin USA. Country of Origin is subject to change.

 Compare this product

Roll over image to zoom.

Web Price

\$233.49

/ each

Qty

2

Add to Cart Shipping Pickup

Expected to arrive Mon. Jul 12.

Ship to 21075 | [Change](#)

Shipping Weight 2.3 lbs

[Ship Availability Terms](#)

