

**Region:** 5

**Location:** DE007

**CSS #:** 31520

**Maximo Work Order No.:** 14545

**Asset #:** NA

**Date Issued:** 8/10/21

**Original Description:** Wall pack exhaust fan- asset 1057 Switch is broken and not getting power to the switch. - \$250 PM credit will apply

**Repairs Needed:**

S&S proposes to replace the slow running motor in the Wall pack exhaust fan - asset 1057. While onsite also look at exhaust fan located at OMS shop building 2 asset number 1057.

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Materials (see attached detail)	--	--	\$1,721.09	--	\$1,721.09
--	NA	SS Labor	12	\$100.00	--	--	\$1,200.00
--	NA	TW Coordination	4	\$80.00	--	--	\$320.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate Includes \$250 PM Credit
16	\$1,520.00	\$1,721.09		\$3,241.09	106%	<b>\$3,185.56</b>



# S&S MECHANICAL

**S&S Mechanical**  
4831 South Crain Highway  
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555  
Fax. 1 - (301) 574-1558  
www.sandsmidatlantic.com

## CUSTOMER QUOTATION NO. 679

Tidewater, Inc.  
Tidewater, Inc  
6625 Selnick Dr.  
Suite A  
Elkridge MD 21075

**Quote Name:** 14545  
**Quote No:** 679  
**Site:** DE007 Olgetown Road  
**Site Contact:**  
**Salesperson:** Lindsay Ruby  
**Created Date:** 08/06/2021  
**Valid For:** 30 Day(s)

**WO#: 14545**

**CSS Ticket Number: 31520**

**Problem:** Replace the slow running motor in the Wall pack exhaust fan- asset 1057. While onsite also look at exhaust fan located at OMS shop bldg 2 asset number 1058.

S&S proposes to remove and replace the slow running fan motor in exhaust fan 1057. S&S will replace the faulty RIB and kill switch in exhaust fan 1058. S&S will then complete a system check to ensure everything is working properly.

### Service

Item	Quantity	Unit Price	Total
Marathon MG639 Fan Motor	1.00	\$569.64	\$569.64
Motor Starter 2AY11	1.00	\$528.23	\$528.23
Prewired Relay 5LE35	1.00	\$23.22	\$23.22
Shipping	1.00	\$100.00	\$100.00
Disposal Fee	1	\$500.00	\$500.00
Electrical Labor Rate	12	\$100.00	\$1,200.00
<b>Sub-Total ex Tax</b>			\$2,921.09
<b>Tax</b>			\$0.00
<b>Total inc Tax</b>			\$2,921.09

<b>Labor</b>	\$1,700.00
<b>Materials</b>	\$1,221.09
<b>Sub-Total ex Tax</b>	\$2,921.09
<b>Tax</b>	\$0.00
<b>Total inc Tax</b>	\$2,921.09



**JIM'S  
ELECTRIC MOTOR  
CO. INC.**

8811 Telegraph Road  
Lorton, Virginia 22079  
(703) 550-8624

Customer: S & S Mid-Atlantic  
Email: lindsay@sandsmidatlantic.com

Date: August 4<sup>th</sup> 2021  
Quote# **M-8278**

Qty	Description	Price Each	EXT Price
1	Marathon MG639: 0.25 HP Explosion Proof Motor, 1 phase, 1800 RPM, 115/208-230 V, 56 Frame, EPNV  LEAD TIME: 2-3 working days ARO		\$474.70
All sales transactions are subject to credit approval. All amounts quoted do not include state, local, or municipal taxes of any kind. Applicable sales tax will be added at the time of sale. This quote is good for 30 days.		Freight	<b>TBD</b>
		Sales Tax	<b>\$</b>
		Total	<b>\$</b>

## Prewired Relays

## FUNCTIONAL DEVICES INC / RIB

# Prewired Relay, 10 to 30V AC/DC, 120V AC, 10A @ 277V, 10A @ 28V, SPDT

Item # 5LE35

Mfr. Model # RIBU1C

UNSPSC # 39121515

Catalog Page # 220

Country of Origin USA. Country of Origin is subject to change.



Tap image to zoom.

Web Price

**\$19.35** / each

Qty

1

**Add to Cart**



2AY11



## Hazardous Location Manual Motor Starters

HUBBELL KILLARK

Motor Starter, Number of Poles 2, 20 A  
Amps AC, 3/4 in Hub Size, Feed-Thru

Item # 2AY11

Mfr. Model # FXSX52

UNSPSC # 39121512

Catalog Page # 250

Country of Origin Mexico. Country of Origin is subject to change.



Tap image to zoom.

Web Price

**\$440.19** / each

Qty

1

Add to Cart



Shipping



Pickup

electrical power to the motor.  
not restrict motor movement. Motor  
must have sufficient movement for  
possible future belt or wheel  
adjustment.

454979

450029



**GREENHECK**

715-359-6171

ASSEMBLED IN USA

MODEL

CHB-098-4

S/N

12461822 1105

MARK

FV-4 OHS

[www.greenheck.com](http://www.greenheck.com)