

Additional Funding Request

VA048	CSS# 31522 # 14547
Description of Repairs	Labor to perform diagnosis of gate issues being experienced at VA048
Diagnosis: Initial Work Order	The gate is not working properly.
Diagnostic Fee	\$ 0
Additional Labor Cost to Perform Repairs	<p>\$ 650</p> <p>Labor \$75/hr x 8</p> <p>Admin Fee: \$50</p>
Additional Material Cost to Perform Repairs	\$ 0
Total Cost of Repair	\$ 650

LoCurrent Systems, LLC

3522 County Highway 11
 Cooperstown, NY 13326
 (607)293-7300
 locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
 6625- A Selnick Drive
 Elkridge, MD 21075

ESTIMATE # 1820**DATE** 07/08/2021**P.O. NUMBER**

Monteith VA048 Diagnose Gate

	ACTIVITY	QTY	AMOUNT
07/08/2021	Services CSS#31522 WO#14547 Monteith, VA USARC VA048 Urgent: Diagnose Gate Issues	1	650.00

Dear Ms. Mascelli:

As per your request, LoCurrent Systems is pleased to provide a quotation to perform diagnosis of Gate issues being experienced at the Monteith, VA USARC VA048.

Cost Breakdown:

(1) man 8 hrs @	
\$75.....	\$600.00
Administrative.....	\$50.00

Grand	
Total.....	\$650.00

The cost for the above mentioned work is \$650.00.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

Thank you for thinking of LoCurrent Systems.

Sincerely,

ACTIVITY	QTY	AMOUNT
Antonietta LoRusso		
	TOTAL	\$650.00

Accepted By

Accepted Date