

**CERTIFICATION OF WORK
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD024 CURTIS BAY Date of Visit: 9/15/21

Contractor Personnel on Site:

- | | |
|-------------------------|----------|
| 1. <u>Keith Pearson</u> | 4. _____ |
| 2. <u>Kenneth Stahl</u> | 5. _____ |
| 3. _____ | 6. _____ |

Service Call Number

CSS# 32132 WO# 14839

Description of Repairs

Arrived on site, replaced 2 loop detectors at Gate 1 + Gate 2. Gate 1 + Gate 2 are now operational. While on site, it was discovered the door release relay is not functioning properly. A followup quotation will be provided.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Keith Pearson Date: 9/15/21

Signed: [Signature]

To be signed by Facility Manager:


By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:


Print Name/Rank: W310 Mark Smith Date: 20210917

Signed: ~~No Personnel Available at~~

E-Mail: ~~the time service was completed~~

[Signature]
Mark H. Smith - civ e mail / m.1





460V 3Ø
USE ONLY COPPER CONDUCTORS
WITH A TEMPERATURE RATING
OF AT LEAST 75° C
Factory Configured

