

Additional Funding Request

MD005	CSS# 33298 WO# 15660				
Description of Repairs	S&S proposes to remove & replace the inlet sensor in boiler #1. S&S will then complete a system check to ensure everything is running properly.				
Diagnosis: Initial Work Order	Need inlet temp sensor for boiler #1. Found during winter changeover.				
Diagnostic Fee	\$ 0				
Additional Labor Cost to Perform Repairs	<p>\$ 600</p> <p>Labor \$100/hr x 6</p>				
Additional Material Cost to Perform Repairs	<p>\$ 175.00</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Materials (see attached detail)</td> <td>1</td> <td>175.00</td> <td>175.00</td> </tr> </table>	Materials (see attached detail)	1	175.00	175.00
Materials (see attached detail)	1	175.00	175.00		
Total Cost of Repair	\$ 775.00				



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 824

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 15660
Quote No: 824
Site: MD005 Broening Highway
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 12/07/2021
Valid For: 30 Day(s)

WO#: 15660

CSS Ticket Number: 33298

Problem: Need inlet temp sensor for boiler #1. Found during winter changeover.

S&S proposes to remove & replace the inlet sensor in boiler #1. S&S will then complete a system check to ensure everything is running properly.

Service

Item	Quantity	Unit Price	Total
Sensor/ 63041677	1.00	\$150.00	\$150.00
Shipping	1.00	\$25.00	\$25.00
HVAC Labor Rate	6	\$100.00	\$600.00
		Sub-Total ex Tax	\$775.00
		Tax	\$0.00
		Total inc Tax	\$775.00
		Labor	\$600.00
		Materials	\$175.00
		Sub-Total ex Tax	\$775.00
		Tax	\$0.00
		Total inc Tax	\$775.00

11:16



< Inbox

3 Messages



Alonzo Jones - BR030

10:55 AM

To: Lindsay Ruby >

My vendor has the part [63041677](#) in stock in New Hampshire cost 125.00 not including tax or shipping .

From: Lindsay Ruby

<lindsay@sandsmidatlantic.com>

Sent: Tuesday, December 7, 2021 10:43:22 AM

To: Alonzo Jones - BR030

Subject: [EXTERNAL] MD005

EXTERNAL

Good morning,

We have a Bosch boiler that needs the "single sensor G1/4 45lg" part number 63041677 (pics attached). Would you be able to send me pricing for this?

[Image-20211022090713 (1).jpg]

[Item 130.jpg]






duplicate

Certified by
Bosch Thermotechnik GmbH

MAWP, water	50 psi
Maximum water temp	200 °F
Minimum relief valve capacity	630 lb/h

Ser.-no. 2530-103-300005-7747014549



Version: 03

Mod GB312 160 Category IV

Input rating max 588 MBtu/h
Output rating 544 MBtu/h
Input rating min 176 MBtu/h
Orifice size nat-gas 17,0mm

Gas supply Pressure 3,5 - 10,5
Electrical Rating 120 V Fuse 5,0 A 60 Hz
Fuel Natural gas

Hot Water Boiler low pressure.

This appliance requires a special venting system.

Refer to installation instructions for parts list and method of installation.

For either direct vent installation or for installation using indoor combination.

ANSI

CSA/CAN/CSA

DRN



ANS Z21.13b-2007

CSA A.6b-2007

FSSA,7C

