

## Additional Funding Request

<b>NY013</b>	<b>CSS# 33733 WO# 16868 Asset# NA</b>				
Description of Repairs	Labor and materials to replace the water fountain due to it leaking for so long, it corroded the lines and drain. Will remove the existing water cooler and plumbing and replace it with a new water cooler and plumbing.				
Diagnosis: Initial Work Order	Repair Water Fountain , Leaking from internal water supply lines				
Diagnostic Fee	\$ 160 TWI \$80/ hr x 2				
Additional Labor Cost to Perform Repairs	\$ 640 TWI \$80/hr x 8				
Additional Cost	\$ 1563.58 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Materials (See attached detail)</td> <td style="width: 10%;">1</td> <td style="width: 20%;">1563.58</td> <td style="width: 30%;">1563.58</td> </tr> </table>	Materials (See attached detail)	1	1563.58	1563.58
Materials (See attached detail)	1	1563.58	1563.58		
Total Cost of Repair	\$ 2363.58				



# Cart

Item	Quantity	Total Price	Item Availability
 <b>ELKAY</b> Refrigerated, Dispenser Design Wall, Water Cooler with Bottle Filling Station, Number of Levels 1 Item #39AM86 Your Price: <b>\$1,206.40</b>	1	<b>\$1,206.40</b>	Expected to arrive <b>Tue.</b> <b>Apr 5</b> using standard ground shipping (additional shipping options available at Checkout.)
 <b>GRAINGER APPROVED</b> P-Trap, For Use With Wall Drain Item #444J39 Your Price: <b>\$3.31</b>	1	<b>\$3.31</b>	Expected to arrive <b>Tue.</b> <b>Apr 5</b> using standard ground shipping (additional shipping options available at Checkout.)
 <b>GRAINGER APPROVED</b> Expansion Anchor Set: Plug Wall Anchor, #12 Thread Dia., Polyethylene, 50 PK Item #32TH83 Your Price: <b>\$11.85</b>	1	<b>\$11.85</b>	Expected to arrive <b>Tue.</b> <b>Apr 5</b> using standard ground shipping (additional shipping options available at Checkout.)

 Chat with an Agent

