

Region: 5

Location: VA048

CSS #: 34075

Maximo Work Order No.: 15970

Asset #: NA

Date Issued: 1/24/22

Original Description: The gate is not working properly not opening and closing consistently.

Repairs Needed:

LoCurrent proposes to replace (1) motherboard, (1) display board, and (1) keypad membrane, and to reprogram and test for proper operation.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Materials (see attached detail)	--	--	\$1,036.51	--	\$1,036.51
--	NA	LoCurrent Labor - 2 men @ 12 hours (includes diagnostic)	24	\$103.75	--	--	\$2,490.00
--	NA	TW Coordination	4	\$80.00	--	--	\$320.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
28	\$2,810.00	\$1,036.51		\$3,846.51	100%	\$3,846.51

LoCurrent Systems, LLC

3522 County Highway 11
 Cooperstown, NY 13326
 (607)293-7300
 locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
 6625- A Selnick Drive
 Elkridge, MD 21075

ESTIMATE # 1913**DATE** 01/24/2022

ACTIVITY	QTY	AMOUNT
Services	1	3,076.51
Follow Up Quotation as per Estimate #1909/Invoice #2083:		3,076.51
Monteith, VA VA048 Replace Motherboard, Display, Keypad Membrane		
Dear Ms. Mascelli:		
As per our findings while on site performing Estimate #1909, LoCurrent Systems is pleased to provide a quotation for the Replacement of (1) Motherboard, (1) Display Board, and (1) Keypad Membrane, and to Reprogram and Test, at the Monteith, VA Facility VA048.		

Cost Breakdown:

(1)
 Motherboard.....\$815.18
 (1) Display
 Board.....\$138.95
 (1) Keypad Membrane.....\$82.38
 (2) men 12hrs @
 \$85/hr.....\$2040.00

Grand
 Total.....\$3076.51

ACTIVITY	QTY	AMOUNT
The cost for the above mentioned is \$3076.51.		
If acceptable, please do not hesitate to contact us.		
Thank you for thinking of LoCurrent Systems.		
Sincerely,		
Antonietta LoRusso		
	TOTAL	\$3,076.51

Accepted By

Accepted Date

LoCurrent Systems, LLC

3522 County Highway 11

Cooperstown, NY 13326

(607)293-7300

locurrent@gmail.com


LOCURRENT
 SYSTEMS, LLC
INVOICE**BILL TO**

Tidewater Inc.

6625- A Selnick Drive

Elkridge, MD 21075

INVOICE # 2083**DATE** 01/24/2022**DUE DATE** 02/23/2022**TERMS** Net 30

ACTIVITY	QTY	RATE	AMOUNT
Services As per Estimate #1909:	1	450.00	450.00

Monteith, VA VA048

Diagnose/Repair if Possible Gate

Dear Ms. Mascelli:

As per your request, LoCurrent Systems is pleased to provide a quotation to Diagnose and Repair if possible the Gate at the Monteith, VA Facility (VA048).

The cost to Diagnose is \$450.00.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

Thank you so much for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

If you have any questions regarding this invoice, please contact Antonietta LoRusso at (607)293-7300.


BALANCE DUE

\$450.00



Have a question? Give us a call at (888) 378-1127

HySecurity Smart Touch Controller Board For Hydraulic Gate Operators - MX4134



Smart Touch Controller Board

\$763.98

HySecurity Smart Touch Controller Board For HydraWedge SM50, HydraSupply XL Universal - MX4134

Call (800) 878-7829

Related Products

Check items to add to the cart or [select all](#)

HySecurity 3V Lithium Battery For Smart Touch Controller / Smart DC Controller - MX000346



\$2.86



Search our shop... CALL (262) 989-9894 M-F 8:00am to 5:00pm CST

GET A QUOTE

SHOP BY CATEGORY

SHOP BY MANUFACTURER

CLICKABLE PARTS FINDER

REQUEST NET 30 TERMS

CONTACT US

NEWS AND BLOG

HYSECURITY MX3356 BOARD, DISPLAY

Manufacturer Hysecurity Item Number MX3356 Write a review No reviews

\$156.17

Quantity

1

ADD TO CART




OLED display board for operators with a 32 character display opening of 2-3/4 x 3/4 inch. Retrofit kit MX3542 required for retrofitting older display boards.

Share

Tweet

Pin It

Google+



HYSECURITY MX3399 KEYPAD, SMART TOUCH CONTROLLER

Manufacturer: Hysecurity Item Number: MX3399 No reviews

1

Chat with us!

\$77.70

CERTIFICATION OF WORK
SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: montieth

Date of Visit: 1-24-22

Contractor Personnel on Site:

1. Keith Pearson
2. Austin Curman
3. _____

4. _____
5. _____
6. _____

Service Call Number

CSS# 34075 WO# 15970 Est. 1909

model # - 222 SS ST Serial # 011400-1615-223

Description of Repairs

Upon arrival at facility found that ants have moved back into Control box and caused damage to the mother board & Display, as well as Command buttons on Controller Cover.

Need New Board, Display and buttons. Estimate to follow

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Keith Pearson Date: 1-24-22

Signed: Keith Pearson


To be signed by Facility Manager:


By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: _____ Date: _____

Signed: _____

E-Mail: _____







Model. No.: 222 SS ST

S/N: 011400-1615-223

 **HySecurity®**

Simple. Reliable. Secure.®

Smart Touch Controller

Open



Previous

Close



Next

Stop




Select



Reset

Green = Operate
Red = Fault
Blue = Menu mode



Menu

