

Additional Funding Request

VA049	CSS# 34099 WO# 16410							
Description of Repairs	Moores proposes labor and materials to remove and replace the burner plate insulation, burner plate inner seal and the rear refractory. Moores will then ensure proper operations.							
Diagnosis: Initial Work Order	Additional efforts - Boilers #4 On unit #4 found the burner plate insulation was cracked and when Moores pulled the burner.							
Diagnostic Fee	\$ 0							
Additional Labor Cost to Perform Repairs	<p>\$ 600</p> <p>Labor \$120/hr x 5</p>							
Additional Material Cost to Perform Repairs	<p>\$ 357.90</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Materials (See attached detail)</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px; text-align: right;">357.90</td> <td style="padding: 2px; text-align: right;">357.90</td> </tr> </table>				Materials (See attached detail)	1	357.90	357.90
Materials (See attached detail)	1	357.90	357.90					
Total Cost of Repair	\$ 957.90							



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

Proposal

January 31, 2022

Quotes are valid for 30 days.

USARC - VA049
6700 Strathmore Rd.
North Chesterfield, VA
Email adam.colopy@tideh2o.net & Mary.Lowery@tideh2o.net

Contact Name Mary Lowery & Adam Colopy
Telephone 0.00
Cell Phone 614-623-9569
Fax Number 0.00

DESCRIPTION OF EQUIPMENT:

Make: BURNHAM
Model: ALP399F-1L07
Serial: 65174827

DESCRIPTION OF PROBLEM:

Technician found the back refractor had fallen and is worn out. The burner insulation crack and fell out when the burner was pulled to clean. Will need to order new insulation and install into the boiler.

DESCRIPTION OF REPAIRS:

Moore's is proposing to remove and replace the burner plate insulation, burner plate inner seal and the rear refractory. Ensure proper operations.

MATERIAL, EQUIP OR PARTS

	Quantity	Sell price
Burner Plate Insulation	1.00	\$ 41.63
Burner Plate Inner Seal	1.00	\$ 109.70
Rear Refractory	1.00	\$ 73.57
Shipping	1.00	\$ 78.00
Truck Fee	1.00	\$ 55.00
Material Total	\$	357.90

LABOR ITEMIZED

		Labor
Labor - One Man	5	\$ 120.00 \$ 600.00
		Labor Total \$ 600.00

Thank you for your business. If you have any questions or concerns, please feel free to contact us via telephone or quotes@mooreselectric.com

Materials	\$	357.90
Labor	\$	600.00

Robert Lowery, Changeout Estimator 434-309-2591
Sabrinia Taylor, Estimator 434-309-2563
James Davis, Estimator 434-309-2568
Marvin Slaughter, Estimator 434-369-3514
Jared Underwood, Estimator 434-306-2446

TOTAL \$ **957.90**

Approved by: _____

In consideration of Moore's Electrical & Mechanical extending credit to the above applicant, the undersigned hereby guarantees unconditionally and irrevocably. The compliance of all terms of the application and agreement, including the payment of any sums within the net terms agreed upon between the customer and Moore's, plus any additional costs such as a 1.5% monthly interest charge starting once an invoice becomes 30 days past due, service charges, legal fees and any means taken in order to collect debt. If it is deemed necessary to litigate, it is agreed that the County or District Court of Campbell County, Virginia shall be the venue of any suit. This guarantee shall remain in full force unless and until notice in writing is sent certified mail and received by Moore's Electrical & Mechanical. Said notice cannot be within 14 days of this signed agreement.

RUN DATE: 1/31/22

CUST PH # 434-369-4374
CUST FAX # 434-369-2230

R.E. MICHEL COMPANY

WHOLESALE DISTRIBUTORS • AIR CONDITIONING • HEATING • REFRIGERATION
EQUIPMENT • PARTS • SUPPLIESwww.remichel.com *make the connectionSM*

R.E. MICHEL COMPANY LLC RICHMOND , VA 232246307

DATE: 1/31/22
 TIME: 9:06:41 AM ET
 SALE TYPE: CHARGE
 ** QUOTE **
 PAGE: 1 OF 1
 ORDER#: 957753 N
 ORDER TYPE:
 FED. I.D.#: 46-2354418
 PHONE: 804-231-4666

CHG WC

YOUR ACCOUNT NO. IS

430920

QUOTE

S MOORE'S ELECTRIC
 O PO BOX 119
 L ALTAVISTA, VA 24517-0119
 D
 T O

S MOORE'S ELECTRIC
 H PO BOX 119
 I ALTAVISTA, VA 24517-0119
 P
 T O

QUOTE NUMBER	CUSTOMER ORDER NUMBER	SALESMAN	SHIP VIA	
95775300	MSLAUGHTER	951890	CPU	

Quantity Ordered	Quantity Shipped	Back Ordered	Stock Number	Description	Unit Price	Extended Price
				DUE TO CURRENT VOLATILE MARKET CONDITIONS, PRICING SUBJECT TO ANY PRICE INCREASE TO/AT TIME OF SHIPMENT. TAX AND FREIGHT NOT INCLUDED.		
1	0	1	2W7830	ALPINE 105650-01 BURNER PLATE INSULATION	34.69	34.69
1	0	1	2W7831	ALPINE 105185-01 BURNER PLATE INNER SEAL, ALP	91.42	91.42
1	0	1	105651-01	REAR REFRACTORY	61.31	61.31
SHIPS IN 5 TO 7 DAYS FROM LANCASTER PA. UPS CHARGES \$35.00						
THANKS FOR SHOP WITH R E MICHEL CO. 24 HOUR CELL PHONE 804-229-5705						

Counterperson: JOLAMBET
VA760 0550

Tax Certificate Number

Sub Total	187.42
Sales Tax	11.25
FREIGHT	
TOTAL ►	198.67

A Family Company Since 1935

** This is NOT an invoice **
 ** DO NOT sign this document as a receipt **