



Invoice

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

May 23, 2022

RE:W/O 16907 CSS#34200 NY001

Boiler

-Service call

- Remove insulation and inspect piping.

Remove decayed piping and reducing collar.
Replace pipe, collar, and insulation.

1 14" x 60" galvanized pipe(Grainger).	186.12
1 14" - 12" reducing coupling (Grainger)	48.16
1 Insulation repair tape.	28.30

262.58

8hrs @ 120.00. 960.00

sub-total. 1222.58

20%profit/OH 244.52

Total. 1467.10

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL