

Additional Funding Request

MD005	CSS# 35020 WO# 16880 Asset# NA							
Description of Repairs	S&S proposes to remove and replace both mop sink faucets in janitor closets on first and second floor.							
Diagnosis: Initial Work Order	Janitor closet sink, 1st floor, leaks. 2nd floor janitor closet faucet will not turn off completely.							
Diagnostic Fee	\$ 250							
Additional Labor Cost to Perform Repairs	<p>\$ 800</p> <p>SS \$100/hr x 8</p>							
Additional Cost	<p>\$ 475.88</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Materials & Shipping</td> <td style="width: 15%;">1</td> <td style="width: 25%;">475.88</td> <td style="width: 20%;">475.88</td> </tr> </table>				Materials & Shipping	1	475.88	475.88
Materials & Shipping	1	475.88	475.88					
Total Cost of Repair	\$ 1525.88							



S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 956

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 16880
Quote No: 956
Site: MD005 Broening Highway
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 03/23/2022
Valid For: 30 Day(s)

WO#: 16880

CSS Ticket Number: 35020

Problem: Janitor closet sink, 1st floor, leaks. 2nd floor janitor closet faucet will not turn off completely.

S&S proposes to remove & replace both mop sink faucets in the janitor closets on the first & second floor.

Service

Item	Quantity	Unit Price	Total
B-665-bstr Faucet	2.00	\$212.94	\$425.88
Shipping	1.00	\$50.00	\$50.00
Diagnosis Fee	1	\$250.00	\$250.00
Plumbing Labor Rate	8	\$100.00	\$800.00
		Sub-Total ex Tax	\$1,525.88
		Tax	\$0.00
		Total inc Tax	\$1,525.88

Labor	\$1,050.00
Materials	\$475.88
Sub-Total ex Tax	\$1,525.88
Tax	\$0.00
Total inc Tax	\$1,525.88



4 Messages

**Benny Leonard**

To: Lindsay Ruby >

12:51PM

**Re: MD005 Quote**

Would this work for you? The B-665-bstr is all I have to offer. \$177.45 each.

On Wed, Mar 23, 2022 at 12:49 PM Lindsay Ruby <lindsay@sandsmidatlantic.com> wrote:

Show Quoted Content

--

Benny Leonard
ATS LLC
7620 PENN BELT DR.
FORESTVILLE MD 20747
301-735-3001
ATSSUPPLY.COM



Service Sink / Mop Sink Faucets

B-0665-BSTR

TAG: [Service Sink Faucet](#)

Architect/Engineering Specifications:

8" wall mount mixing faucet with rough chrome plated brass body, rough chrome plated brass spout with vacuum breaker, pail hook and garden hose male outlet, compression cartridges with spring checks, lever handles, 1/2" NPT female inlets, built-in service stops in body and upper support rod. Certified to ASME A112.18.1/CSA B125.1 NSF 61-Section 9, NSF 372 and ASSE 1001. Meets ADA ANSI/ICC A117.1 requirements.

Job Name _____
Model Specified _____ Quantity _____
Variations Specified _____
Date _____





