

## Additional Funding Request

Submitted: **05/31/22**

<b>NY127</b>	<b>CSS 35351 WO 16874</b>			
Description of Repairs	Labor and Materials replace card reader on the main door.			
Original SC Investigative Diagnosis	<b>\$0</b>			
Diagnosis: Initial Work Order	Repair CAC card reader on the main door of the OMS building. The Reader just blinks red, and you cannot enter your pin number to gain access.			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	<b>Materials: \$ 475.00</b>			
	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>
	<b>Materials (See attached for details)</b>	<b>1</b>	<b>\$475.00</b>	<b>\$475.00</b>
Additional Labor Cost to Perform Repairs	<b>Labor: \$680.00</b> 8 hours each/ \$85			
<b>Total Cost of Repair</b>	<b>\$1155.00</b>			

LoCurrent Systems, LLC  
3522 County Highway 11  
Cooperstown, NY 13326  
(607)293-7300  
locurrent@gmail.com



# Estimate

**ADDRESS**

Tidewater Inc.  
6625- A Selnick Drive  
Elkridge, MD 21075

**ESTIMATE #** 2003  
**DATE** 04/29/2022

ACTIVITY	QTY	AMOUNT
<b>Services</b>	1	1,155.00
Nichols, NY USARC		
Replace Reader		

Dear Mr. Brown:

As per your request, LoCurrent Systems is pleased to provide a quotation to Replace (1) Reader at the Nichols, NY USARC.

Cost Breakdown:

(1) Two-Factor  
Reader.....\$475.00  
(1) men 8 hours @  
\$85/hr.....\$680.00  
  
Grand  
Total.....\$1,155.00

The cost for the above mentioned is \$1,155.00.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

Thank you so much for thinking of LoCurrent Systems.

Sincerely,

ACTIVITY	QTY	AMOUNT
----------	-----	--------

Antonietta LoRusso

TOTAL

\$1,155.00

Accepted By

Accepted Date