

Additional Funding Request

Submitted: 6/23/22

VA049	CSS 620 WO 17767								
Description of Repairs	Clean and Inspect the interior gutter system, elbows and downspouts on the Army Reserve Building located at: 6700 Strathmore Road Richmond VA. 23237 Gutter cleaning cost is based on a minimum cost for the first 100 Linear Feet of gutter being cleaned. Theis cost is \$350.00. We then charge an additional \$2.00 per Linear Feet of gutter to be cleaned after the initial 100 LF. We have your gutter footage as 1000 LF. \$350.00 for the first 100 LF and then \$2.00 per foot for the remaining 900 LF, to total: \$2,150.00 Approve this estimate and make a deposit to have our office call to schedule the cleaning. We are currently scheduling about two-three weeks out.								
Original SC Investigative Diagnosis	\$0								
Diagnosis: Initial Work Order	Roof drains and gutters need to be cleaned. Rag weed clogging drains								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 5px;">ITEM</th> <th style="text-align: left; padding: 5px;">QUANTITY</th> <th style="text-align: left; padding: 5px;">UNIT PRICE</th> <th style="text-align: left; padding: 5px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 5px;"></td><td style="text-align: left; padding: 5px;"></td><td style="text-align: left; padding: 5px;"></td><td style="text-align: left; padding: 5px;"></td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL				
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Additional Labor Cost to Perform Repairs	Labor: \$2,150 Brothers that only do Gutters Labor \$350/100 LF Labor \$2.00/ 1 LF x 900								
Total Cost of Repair	\$2,150								



Brothers that just do Gutters
7305 Hancock Village Drive
PMB #500 Chesterfield, VA 23832

Phone: 804-823-5633
Email: request@brothersgutters.com
Web: <http://www.brothersgutters.com>

Estimate
EST 57353

Work Location

Army Reserve
6700 Strathmore Rd
Richmond, VA 23237



Estimate Date
6/16/2022

Solutionist
Steve Huffman

Summary: Cleaning Estimate

Scope: Clean and inspect the interior gutter system, elbows and downspouts on the Army Reserve Building located at: 6700 Strathmore Road Richmond VA. 23237 Gutter cleaning cost is based on a minimum cost for the first 100 Linear Feet of gutter to be cleaned. This cost is \$350.00. We then charge an additional \$2.00 per Linear Feet of gutter to be cleaned after the initial 100 LF. We have your gutter footage as 1000 LF. \$350.00 for the first 100 LF then \$2.00 per foot for the remaining 900 LF, to total: \$2,150.00 Approve this estimate and make a deposit to have our office call to schedule the cleaning. We are currently scheduling about two-three weeks out. Please contact me directly with any additional questions at: Steveh@brothersgutters.com, or call/text (804) 690-4280 for a quicker response. Thank you! Steve

Item	Description
Interior Gutter Cleaning - Base	Cleaning of the interior of a gutter system, elbows and downspouts either by hand or leaf blower. All leaves and debris will be discarded in nearby woods or completely removed from the premises. Base pricing includes up to 100 feet of gutter.
Interior Gutter Cleaning - Additional Footage	Additional footage to be cleaned exceeding 100 Feet.
	Subtotal \$2,150.00
	Tax \$0.00
	Total \$2,150.00

Payment via No Payment, ending #, in the amount of \$0.00, was received on 6/23/2022.

By affixing my signature hereto, I represent that I have read this proposal and accept it as written, and agreeable to me. I understand that I have the legal right to cancel up to three (3) days from the date of signing this contract. I am requesting that The Brother That Just Do Gutters a/k/a Water-flow Gutter Solutions proceed to order materials and schedule work. I further understand that there is a 50% deposit required to schedule my installation.

Customer Signature: _____

Date: _____ 6/23/2022

Pricing is valid for 30 Days



Photos Before



Rear main entrance to building.



Right rear section of building.



Right front corner of building.



Right front section of building.



Left front corner of building.



Left side section of building.



Left side section of building.



Left rear corner of building.

