

## Additional Funding Request

Submitted: 6/13/22

<b>MD002</b>	<b>CSS 804 WO 17801</b>			
Description of Repairs	Labor and Materials to replace 20 bulbs in the kitchen and change out 2 ceiling tiles			
Original SC Investigative Diagnosis	<b>\$ 160</b>			
Diagnosis: Initial Work Order	Building #1- In the kitchen there are 22 lights that need to be replaced, diffusers and 2 ceiling tiles			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	<b>Materials: \$ 289.80</b>			
	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>
	<b>Materials (See attached for details)</b>	<b>1</b>	<b>\$289.80</b>	<b>\$289.80</b>
Additional Labor Cost to Perform Repairs	<b>Labor: \$800</b> 10 hours each/ \$80			
<b>Total Cost of Repair</b>	<b>\$1249.80</b>			



# WORK ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>		
Assigned Technician(s):	John Brown		

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace 20 bulbs in the kitchen and change out 2 ceiling tiles

LABOR/MATERIAL		MATERIAL/SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT	
ITEM	QUANTITY				
Labor			10	\$800.00	
Materials Cost	1	\$289.80		\$289.80	
Diagnostic Labor			2	\$160.00	
SUB-TOTAL COSTS:		Materials Total	\$289.80	Labor	\$960.00
TOTAL			\$1249.80		



Tap image to Zoom

GE CURRENT

**Linear LED Bulb: T8, Medium Bi-Pin (G13), 4 ft Nominal Lg, 32 W LFL, 14 W Watts, 2050 lm**

Item # **467W20**

Mfr. Model # **LED14ET8/G/4/850**

UNSCSP # **39112102**

Catalog Group # **467W20**

Catalog Page # **480**

Country of Origin **China. Subject to Change.**

Your Price

**\$11.50** / each

Qty

20

Add to Cart

Availability Information







