

Additional Funding Request

NY127	CSS# 89611 WO# 19211			
Description of Repairs	Labor and materials to replace the door springs on the roof hatch with new springs and hardware			
Diagnosis: Initial Work Order	Repair roof access door. Door hardware is broken			
Diagnostic Fee	\$160.00			
Additional Labor Cost to Perform Repairs	\$ 240.00 TWI Labor \$80.00 x 3			
Additional Material Cost to Perform Repairs	\$ 466.62			
	Materials (See attached detail)	1	466.62	466.62
Total Cost of Repair	\$ 866.62			


[About Us](#)
[Contact Us](#)
[FAQ](#)
[Manufacturers](#)
[Products](#)
[Shipping](#)
[Advanced Search](#) ← FIND ANYTHING QUICKLY


3 Items In Cart
TOTAL: \$388.85

[CART CHECKOUT](#)
[Continue Shopping](#)
[Estimate Shipping](#)
[Order Help](#)

Browse by Category

[Adhesives](#)
[Backer Rod](#)
[Caulk & Sealants](#)
[Clean Up](#)
[Concrete Items](#)
[Deck Coatings](#)
[Drains](#)
[EPDM](#)
[Eternabond](#)
[Fasteners](#)

Your current order is displayed below. To remove an item from the order, click Remove. To move an item to your Saved Cart to be purchased at a later time, click Save Cart. To change the quantity of an item, change the number displayed in the Quantity field and then click Update.

Summary of Your Order

Product	Qty	Price	Status	Total	Options
JL-RHGI-RETRO-2-GH Roof Hatch Replacement Shock Kit (1-pair)	1	\$140.95	OK	\$140.95	REMOVE SAVE CART
JL-RHGIZ-A388 Roof Hatch Replacement Shock Kit, Old Style (1)	2	\$123.95	OK	\$247.90	REMOVE SAVE CART

☐ Ship To Multiple Addresses

[Email Cart](#)
[Update Quantity](#)

Order Total

Merchandise Total: \$ 388.85

Order Total: \$ 388.85

A [CSG Group](#)
Company

Recent Views
Pages

[shoppingcart](#)
[Skylight Hatch](#)

Products

[Roof Hatch Replacement Shock Kit \(1-pair\)](#)
[Roof Hatch Replacement Shock Kit, Old Style \(1\)](#)
[Roof Hatch Replacement Shock Kit \(1-pair\)](#)




Shop with
Peace of Mind

CUSTOMER REVIEWS

4.2/5



PayPal



Shipping Charges and \$2 Handling Fee are



