

SERVICE REPORT

DATE 10-3-23 ARRIVAL TIME 10:00 DEPARTURE TIME 3:00 JOB/TCK. NO. 191326

CUSTOMER P.O. NO. CSS# 90984

JOB NAME/LOCATION USARC - Abingdon VA001

SERVICE REQUESTED *(28) Investment is labor and material to replace the B&G HW Pump (S# 179056LF) and motor.*

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site and checked in with customer. Got ladders and all tools and equipment needed for job into boiler room. Confirmed bad motor and pump and made sure no power was to unit. Unwired motor and hooked up chain fall to pump. Unbolted pump and lowered it down with chain fall. Got new pump and raised it up with fall. Bolted new pump in and opened valves and confirmed no water leaks. Wired up new motor and turned power back on and confirmed pump was rotating the correct way. let pump run and made sure it had no water leaks. Cleaned up all tools and equipment checked out with customer did paper work and left.

NATURE OF WORK

Regular Service _____
Quoted Service _____
Start-up/Warranty _____
SPD _____
Contract Service _____
Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES _____ NO X EXPLAIN _____

SIGNATURE _____

Customer Representative