

Additional Funding Request

NY067	CSS# 92337 WO# 21462				
Description of Repairs	Labor and material to a.) Install Elkay drinking fountain with filter and bottle filler unit. b.) Requires relocating plumbing and electric in masonry wall to accommodate newer model to acceptable height.%				
Diagnosis: Initial Work Order	There is a drinking fountain across from room 136a that will not drain.				
Diagnostic Fee	NA				
Additional Labor Cost to Perform Repairs	$14 \times 100.00 = \$1400.00$ Credit of 2 hours x \$85.00 $= \$170$ Total = \$1230.00				
Additional Material Cost to Perform Repairs	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Materials (See attached detail)</td> <td style="padding: 2px;">NA</td> <td style="padding: 2px;">180.00</td> <td style="padding: 2px;">180.00</td> </tr> </table>	Materials (See attached detail)	NA	180.00	180.00
Materials (See attached detail)	NA	180.00	180.00		
Total Cost of Repair	\$ 1410.00				

HUNOLD CONTRACTING INC.
72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: Karlee
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE
6/13/23

Quantity	Description	Amount
1	USARC Utica, NY. NY067 CSS 92337 WO 21462 Install Elkay drinking fountain with filter and bottle filler unit. Requires relocating plumbing and electric in masonry wall to accommodate newer model to acceptable height. Material: (mortar, block, supply, drain, GFI, box) \$180 Labor: (14 hours @ \$100/ hr.) \$1400 Price includes all labor, equipment and material.	1580.00
	Sub total	1580.00
	Sales Tax	N/A
	Total	1580.00

Signature _____ Date _____

Signature _____ Date _____