

Additional Funding Request

NY067	CSS# 92891 WO# 21754							
Description of Repairs	Labor and material to a.) Repair roof leaks and ceiling tiles above Main lobby, Common area, Room 111.							
Diagnosis: Initial Work Order	Repair leaks and replace ceiling tile Locations of leaks: . Near the copier in the common area on the 2nd level . Main entrance lobby area . Men's restroom off the drill hall (room 111)							
Diagnostic Fee	NA							
Additional Labor Cost to Perform Repairs	$12 \times \$100.00 = \1200.00							
Additional Material Cost to Perform Repairs	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Materials (See attached detail)</td> <td style="padding: 2px;">NA</td> <td style="padding: 2px;">435.00</td> <td style="padding: 2px;">435.00</td> </tr> </table>				Materials (See attached detail)	NA	435.00	435.00
Materials (See attached detail)	NA	435.00	435.00					
Total Cost of Repair	\$ 1635.00							

HUNOLD CONTRACTING INC.

72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: Karlee
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE**3/31/23**

Quantity	Description	Amount
1	USARC Utica, NY. CSS# 92891, NY067 Repair roof leaks and ceiling tiles above: Main lobby Common area Room 111 Material: (Roof boots, mastic, flashing material, tiles) \$435 Labor: (12 hours @ \$100/ hr.) \$1200 Price includes all labor, equipment and material.	1635.00
	Sub total	1635.00
	Sales Tax	N/A
	Total	1635.00

Signature _____ Date _____

Signature _____ Date _____