

Additional Funding Request

NY067	CSS# 93012 WO# 21767		
Description of Repairs	Labor and material to a.) diagnose and Repair (if possible) the Non-functioning Rear Entrance Gate		
Diagnosis: Initial Work Order	The rear entrance gate is not functioning. It appears that it is not receiving power.		
Diagnostic Fee	NA		
Additional Labor Cost to Perform Repairs	2 Men @ (8) hours x 85.00 = \$1360.00		
Additional Material Cost to Perform Repairs	Materials (See attached detail)	NA	NA
Total Cost of Repair	\$ 1360.00		

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 2235
DATE 04/11/2023

P.O. NUMBER

Utica, NY Diag & Rep Rear Gate

ACTIVITY	QTY	AMOUNT
Services Utica, NY USARC NY067 Diagnose & Repair if possible Non- functioning Rear Entrance Gate CSS #93012 WO #21767	1	1,360.00

Dear Ms. Demain:

As per your request, LoCurrent Systems is pleased to provide a quotation to Diagnose and Repair (if possible) the Non-functioning Rear Entrance Gate at the Utica, NY USARC Facility.

Cost Breakdown:

(2) men 8 hours @
\$85/hr.....\$1,360.00

The total cost for the above mentioned work is \$1,360.00

If acceptable, please do not hesitate to contact us.

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

TOTAL

\$1,360.00

Accepted By

Accepted Date