

Additional Funding Request



NY127	CSS# 93138 WO# 22119			
Description of Repairs	Labor and material to a.) remove the old refrigerator and water line and install the new refrigerator and water line and test for proper operation			
Diagnosis: Initial Work Order	Refrigerator in breakroom leaking water from underneath. Water supply to ice dispenser has been turned off.			
Diagnostic Fee	NA			
Additional Labor Cost to Perform Repairs	(6) hours x 80.00 = \$480.00			
Additional Material Cost to Perform Repairs	<table><tr><td>Materials (See attached detail)</td><td>\$1248.00</td></tr></table>		Materials (See attached detail)	\$1248.00
Materials (See attached detail)	\$1248.00			
Total Cost of Repair	\$ 1,728.00			

pb would like to

share their cart with you

[View Cart](#)

pb's Cart

Item	In Store	Qty	Item Total
 Whirlpool 21.4 cu. ft. Side by Side Refrigerator in Fingerprint Resistant Stainless Steel Model #WRS321SDHZ Store SKU #1002722001	 Aisle Bay	1	\$1,248.00

Subtotal	\$1,248.00
Shipping	\$0
Sales Tax	\$0
Est. Total	\$1,248.00




Whirlpool®

FULL LOAD AMP /
DEMANDE DE COURANT
A PLEINE CHARGE
OZ R-134a

6.5


3.7

TYPE 21MTFA


MFG. DATE/
DATE DE FABR. 03 - 14

Whirlpool is a Registered Trademark of/ Marque déposée de Whirlpool, U.S.A. Benton Harbor MI 49022. Emplol licencé par / Whirlpool Canada LP, Mississauga, ON L5M 5A7 / Toronto, Ontario Canada

60 HZ / 1 PHASE / 115V
DESIGN PRESSURE 140 P.S.I. LOW 330 P.S.I. HIGH
PRESSION DE SERVICE 140 PSI BASSE 330 PSI HAUTE



MOD. WRT771REYM00



SER. VS41296168

HOUSEHOLD REFRIGERATION
RÉFRIGÉRATEUR DOMESTIQUE

APPLICATION FAMILIALE

ALSO LISTED
IN ACCORDANCE
WITH ENERGY STAR
3179

14623 142A



VERIFIED
FOR ENERGY
PERFORMANCE

RENOUVEAU
ENERGETIQUE
VERIFIÉ

Energy Star
CERTIFIED
BY 100000