

Additional Funding Request

NY067	CSS# 93318 WO# 22134		
Description of Repairs	<p>Labor and material to a.) Repair stained ceiling tiles:</p> <p>Mechanical room, drill hall, common area near Marauder Blvd</p>		
Diagnosis: Initial Work Order	<p>Repair ceiling tile</p> <p>There are multiple ceiling tiles that need to be replaced. Locations listed below:</p> <ul style="list-style-type: none"> - Over the doorway leading into the drill hall from the arms room area. - In the hallway in front of room 120 - In the common area downstairs along the wall nearest to the Marauder Blvd. side. - In the common area downstairs near the mechanical room doors and above room 042 		
Diagnostic Fee	NA		
Additional Labor Cost to Perform Repairs	(7) hours x 100.00 = \$700.00		
Additional Material Cost to Perform Repairs	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Materials (See attached detail)</td> <td style="padding: 2px;">\$35.00</td> </tr> </table>	Materials (See attached detail)	\$35.00
Materials (See attached detail)	\$35.00		
Total Cost of Repair	\$ 735.00		

HUNOLD CONTRACTING INC.
72 PENDERGAST ROAD
PHOENIX, NY 13135
Cell # 315-247-5898

Customer:

Tidewater Attn: Karlee
6625 Selmick Dr., Suite A
Elkridge, MD 21075

ESTIMATE
5/3/23

Quantity	Description	Amount
1	USARC Utica, NY. NY067 CSS 9313 Repair stained ceiling tiles: Mechanical room, drill hall, common area near Marauder Blvd Material: (Tiles) \$35 Labor: (7 hours @ \$100/ hr.) \$700	735.00
	Price includes all labor, equipment and material.	
	Sub total	735.00
	Sales Tax	N/A
	Total	735.00

Signature _____ Date _____

Signature _____ Date _____