

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 8-16-23 ARRIVAL TIME 7:30 DEPARTURE TIME 10:00 JOB/TCK. NO. 196500

CUSTOMER P.O. NO. _____

JOB NAME/LOCATION USARC - Rainelle WV034SERVICE REQUESTED (6) Investment is to replace the burner control on Burnham Boiler #1.

Manufacture: <u>Burnham</u>				
Model#: <u>APX500F-2L07</u>				
Serial#: <u>65260495</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested☐ Leak Found☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site, checked in with customer. Went to boiler room and took old boiler burner control off and installed the flame card and purge card out of the old controller into the new one. Then turned boiler on and it started up but i noticed the pumps were not running so i turned it off and then went and found the the flow switch. I tested and it was closed when there was no water flow and when i went to step down i hit one of the gauges and it snapped off. I hurried up and shut bothe valves feed the pump and it did not slow the pressure down so one of the valves was leaking through. I went and turned off a few more valves and got it to slow down. Then i used a screw driver and pulled the broke nipple out and replaced it with one i had on my van. I the

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
1		Burner controls		Hvac	232684

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
1154 Shawn Shelton	4		1		5					

JOB COMPLETE YES X NO _____ EXPLAIN Flow switch needs replaced.

SIGNATURE _____

Customer Representative

SERVICE REPORT

CUSTOMER P.O. NO. _____

SERVICE REQUESTED

Manufacture: <i>Burnham</i>				
Model#: <i>APX500F-2L07</i>				
Serial#: <i>65260495</i>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: _____

Total Charge: _____

reopened the valves and left the VFD and PUMP off in case it got water in it because water sprayed every where and going to let it dry out before restarting it. I left the boiler off also because the flow switch was bad and did not want to damage the boiler by running it with out water flow. Told client what happened and also what i had done. Then cleaned up tools and done paper work.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

[illegible][illegible]

JOB COMPLETE YES _____ NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative