

## Additional Funding Request

NY127	CSS# 93779 WO# 22721							
Description of Repairs	Labor and material to a.) clean the condenser coils on 2 Liebert mini mate air conditioning systems and check refrigerant charges							
Diagnosis: Initial Work Order	OMS TR room AC not working. Computer room a/c not working room alarm going off indicating high temperature							
Diagnostic Fee	NA							
Additional Labor Cost to Perform Repairs	4 Hours x \$128.00 = \$512.00							
Additional Material Cost to Perform Repairs	<table><tr><td>Misc materials (See attached detail)</td><td>NA</td><td>\$50.00</td><td>\$50.00</td></tr></table>				Misc materials (See attached detail)	NA	\$50.00	\$50.00
Misc materials (See attached detail)	NA	\$50.00	\$50.00					
Total Cost of Repair	\$ 562.00							



June 12, 2023

Tidewater  
US Army Corps of Engineers  
881 Stanton Rd  
Nichols, NY 13812

Attn: Karlee Demain

Re: clean condenser coils and check refrigerant charge

Ms. Demain,

Postler & Jaeckle Service is pleased to provide a quote to clean the condenser coils on 2 Liebert mini mate air conditioning systems and check refrigerant charges. Your cost for this service will be \$512.00 for labor and \$50.00 materials for a total of \$562.00. This quote is based on work being performed during normal working hours of 8:00am to 4:30pm Monday through Friday. Thank you for the opportunity to provide this quote for your facility. Please contact me with any questions.

Sincerely,

**DAVE HENDEE**

Field Sales Support

**Postler & Jaeckle Corp.**

**2000 Lake Rd., Elmira, NY 14903**

**T 607-739-8303 | C 607-215-6523**

E: [dhendee@postler.com](mailto:dhendee@postler.com)