

## Additional Funding Request

<b>NY127</b>	<b>CSS# 9478 WO# 19188</b>				
Description of Repairs	Labor and materials to remove the old filters and install (4) new PENTAIR/EVERPURE				
Diagnosis: Initial Work Order	Water filters over sink in kitchen need replacement				
Diagnostic Fee	\$ 160.00				
Additional Labor Cost to Perform Repairs	\$320.00 TWI Labor \$80 an hour x 4				
Additional Material Cost to Perform Repairs	\$ 607.86 <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Materials (See attached detail)</td> <td>1</td> <td>607.86</td> <td>607.86</td> </tr> </table>	Materials (See attached detail)	1	607.86	607.86
Materials (See attached detail)	1	607.86	607.86		
Total Cost of Repair	\$ 1087.86				

**To:**

TIDEWATER INC  
6625 SELNICK DR #A  
ELKRIDGE MD 21075-6220

**Information**

Date 09/01/2022  
Customer Account Number 885295220  
Grainger Quote Number 47191697  
Customer Job Number  
Contract Number  
Grainger Representative John R Romano  
Phone Number  
Fax Number  
Email  
Grainger Tax ID 36-1150280

Item	Description Manufacturer Name & Model	Cat. Pg. #	Qty	\$ Quote	Ext. Price	Start Date	Exp. Date
53GK26	Quick Connect Filter,0.5 micron,1.7 gpm PENTAIR/EVERPURE EV961256-75 Country of Origin: USA		2	126.60	253.20	09/01/2022	12/31/2022
5WFG0	Quick Connect Filter,2 gpm PENTAIR/EVERPURE EV979902-75 Country of Origin: USA		2	111.60	223.20	09/01/2022	12/31/2022
5WFG2	Filter Cartridge,10 micron,20 1/8" H PENTAIR/EVERPURE EV953420-75 Country of Origin: Taiwan		2	15.45	30.90	09/01/2022	12/31/2022
						Total \$	507.30

All orders are subject to the terms and conditions in your current contract with Grainger or to Grainger's current Terms of Sale as set forth on Grainger.com

Thank You!

Visit us at [grainger.com](http://grainger.com)