

Date: 8/26/2024

Region: 4A
FAC ID: NY070CSS No.: 95245
Maximo WO No.: 16618

Asset #: NA

Priority: Urgent

**Original Work Request:**

Heated Storage: follow up repairs for the initial investigation under WO 14248.
 UH-1 draft inducer and gas valve replacement required.
 UH-2 fan motor & blade, transformer, sequencer, and high-limit replacement required.
 UH-3 pilot assembly, ignitor, and ignition module replacement required.
 UH-4 draft motor and sequencer replacement required

Description of Repairs Needed:

Labor and materials to a.) replace draft inducer assembly and gas valve on UH-1, b.) replace fan motor, blade, transformer, sequencer, and high limit on UH-2, c.) replace pilot assembly, and ignition module on UH-3, d.) replace draft inducer assembly, and sequencer on UH-4.

Labor:

	Labor Hrs	Labor Rate	Total
Labor for UH-1	6	\$ 128.00	\$ 768.00
Trip	1	\$ 50.00	\$ 50.00
Labor for UH-2	6	\$ 128.00	\$ 768.00
Trip	1	\$ 50.00	\$ 50.00
Labor for UH-3	6	\$ 128.00	\$ 768.00
Trip	1	\$ 50.00	\$ 50.00
Labor for UH-4	6	\$ 128.00	\$ 768.00
Trip	1	\$ 50.00	\$ 50.00

Material List:

	Quantity	Cost	Total
Draft Induser assembly	2	\$ 658.67	\$ 1,317.34
Gas valve	1	\$ 638.33	\$ 638.33
Fan motor/blade	1	\$ 901.25	\$ 901.25
Transformer	1	\$ 446.15	\$ 446.15
Sequencer	2	\$ 412.31	\$ 824.62
High limit	1	\$ 142.29	\$ 142.29
Pilot assembly	1	\$ 307.00	\$ 307.00
Ignition module	1	\$ 435.00	\$ 435.00
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 3,272.00	\$ 5,011.98	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$8,283.98	\$994.08	\$497.04	\$9,775.10

WORK ESTIMATE

Prepared by:

Postler & Jeackle Corp
615 South Ave
Rochester NY 14620

Prepared for:

Tidewater, Inc.
6625 Selknick Drive, Suite A
Elkridge, MD 21075

Date: 8/26/2024 CSS #: 95245

FAC ID: Site Address: 515 Ridge Rd Webster NY

DESCRIPTION OF WORK			
UH-1: draft inducer and gas valve need to be replaced we recommend replacing the inducer assembly and gas valve			

LABOR	QTY	UNIT/RATE	TOTAL
mechanic	6	\$128.00	\$768.00
trip charge	1	\$50.00	\$50.00
MATERIAL & PART NO	QTY	UNIT/RATE	TOTAL
draft inducer assembly	1	\$658.67	\$658.67
gas valve	1	\$638.33	\$638.33
			\$0.00
			\$0.00
			\$0.00
			\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
			\$0.00
			\$0.00
			\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$818.00
	MATERIAL TOTAL		\$1,297.00
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$2,115.00

Accepted By: _____

Date: _____

Prepared by:

Postler & Jeackle Corp
615 South Ave
Rochester NY 14620

Prepared for:

Tidewater, Inc.
6625 Selknick Drive, Suite A
Elkridge, MD 21075

Date: 8/26/2024 CSS #: 95245

FAC ID: 16618
Site: 515 Ridge Rd Webster NY
Address:

DESCRIPTION OF WORK			
UH-2: Heater needs fan motor, blade, transformer, sequencer, and high limit we recommend replacing the fan motor, blade, transformer, sequencer, and high limit			

LABOR	QTY	UNIT/RATE	TOTAL
mechanic	6	\$128.00	\$768.00
trip charge	1	\$50.00	\$50.00
MATERIAL & PART NO	QTY	UNIT/RATE	TOTAL
fan motor/blade	1	\$901.25	\$901.25
transformer	1	\$446.15	\$446.15
sequencer	1	\$412.31	\$412.31
high limit	1	\$142.29	\$142.29
			\$0.00
			\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
			\$0.00
			\$0.00
			\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$818.00
	MATERIAL TOTAL		\$1,902.00
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$2,720.00

Accepted By: _____

Date: _____

Prepared by:

Postler & Jeackle Corp
615 South Ave
Rochester NY 14620

Prepared for:

Tidewater, Inc.
6625 Selknick Drive, Suite A
Elkridge, MD 21075

Date: 8/26/2024 CSS #: 95245

FAC ID: 16618
Site: 515 Ridge Rd Webster NY
Address:

DESCRIPTION OF WORK			
UH-3: Needs new pilot assembly and ignition module we recommend replacing the pilot assembly and ignition module			

LABOR	QTY	UNIT/RATE	TOTAL
mechanic	6	\$128.00	\$768.00
trip charge	1	\$50.00	\$50.00
MATERIAL & PART NO	QTY	UNIT/RATE	TOTAL
pilot assembly	1	\$307.00	\$307.00
ignition module	1	\$435.00	\$435.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
			\$0.00
			\$0.00
			\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$818.00
	MATERIAL TOTAL		\$742.00
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$1,560.00

Accepted By: _____

Date: _____

WORK ESTIMATE

Prepared by:

Postler & Jeackle Corp
615 South Ave
Rochester NY 14620

Prepared for:

Tidewater, Inc.
6625 Selknick Drive, Suite A
Elkridge, MD 21075

Date: 8/26/2024 CSS #: 95245
FAC ID: WO #: 16618
Site: 515 Ridge Rd Webster NY
Address:

DESCRIPTION OF WORK			
UH-4: Needs new draft inducer and sequencer we recommend replacing the draft inducer assembly and sequencer			

LABOR	QTY	UNIT/RATE	TOTAL
mechanic	6	\$128.00	\$768.00
trip charge	1	\$50.00	\$50.00
MATERIAL & PART NO	QTY	UNIT/RATE	TOTAL
draft inducer aseembly	1	\$658.67	\$658.67
sequencer	1	\$412.31	\$412.31
			\$0.00
			\$0.00
			\$0.00
			\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
			\$0.00
			\$0.00
			\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$818.00
	MATERIAL TOTAL		\$1,070.98
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$1,888.98

Accepted By: _____

Date: _____