

Date: 2/16/2024

Region: 4C
FAC ID: WV014

CSS No.: 96722
Maximo WO No.: 15189

Asset #: NA

Priority: Routine



Original Work Request:

Repair 2 sections of lights in the EST building. Checked breaker, 2 rows of lights won't come on at all.

Description of Repairs Needed:

Labor and material to a.) replace the (Ceiling Sensor WattStopper C1-200) and test for proper operation.

Lead time is 1 week.

Labor	Labor Hrs	Labor Rate	Total
Technician	4	\$ 100.00	\$ 400.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
(Ceiling Sensor WattStopper C1-200)	1	\$ 190.51	\$ 190.51

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 400.00	\$190.51	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$590.51	--	--	\$590.51

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selkirk Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 2/16/2024 CSS #: 96722
FAC ID: WV014 WO #: 15189

DESCRIPTION OF WORK			
Labor and material to a.) replace the (Ceiling Sensor WattStopper C1-200) and test for proper operation. Lead time is 1 week.			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	4	\$100.00	\$400.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
(Ceiling Sensor WattStopper C1-200)	1	\$190.51	\$190.51
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL	\$400.00	
	MATERIAL TOTAL	\$190.51	
	EQUIPMENT TOTAL	\$0.00	
TOTAL COST:			\$590.51

Accepted By: _____

Date: _____