

## SERVICE REPORT

DATE 2024 5 24 ARRIVAL TIME \_\_\_\_\_ DEPARTURE TIME \_\_\_\_\_ JOB/TCK. NO. 205441

CUSTOMER P.O. NO. WO#15407 CSS97007

**JOB NAME/LOCATION** *USARC - South Ridge*

**SERVICE REQUESTED** (28) Labor to troubleshoot AHU-3 & 4, replace OAD on AHU-4, 7, and 8, and replace EF Motor.

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO.**

Arrived on site, checked in with customer. Began disassembling exhaust fan motor housing. Recieved service call. Spoke with POC and will return tuesday to complete work. COW will be presented tuesday after work is complete.

### NATURE OF WORK

Regular Service \_\_\_\_\_  
Quoted Service \_\_\_\_\_  
Start-up/Warranty \_\_\_\_\_  
SPD \_\_\_\_\_  
Contract Service \_\_\_\_\_  
Energy Management \_\_\_\_\_

### PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

### SUMMARY OF TIME

[illegible]

JOB COMPLETE YES \_\_\_\_\_ NO X EXPLAIN \_\_\_\_\_

SIGNATURE \_\_\_\_\_

Customer Representative