

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 2024 5 31 ARRIVAL TIME 7:30 DEPARTURE TIME 10:00 JOB/TCK. NO. 206891CUSTOMER P.O. NO. CSS#9746JOB NAME/LOCATION USARC - Rainelle WV035SERVICE REQUESTED (6) Investment is to replace the Electrode Igniters for the Oil Burner on Burnham Boiler (M# V9A/V11; S#

Manufacture: <u>Burnham</u>				
Model#: <u>V9A/V11</u>				
Serial#: <u>123445</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested☐ Leak Found☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site, checked in with customer. Went to the boiler room and took the burner out and then changed out the old electrodes and replaced them with new ones. Had to measure them out to get the right distance from the nozzle. I then installed it back in place and fired the boiler back up. It lite once so i turned it off and back on. It would not lite again so i pulled it back out and moved it out another 1/16th of an inch and then the boiler lit everytime. I then let it run a few cycles and made sure it was going to keep lighting. Once it did i then turned it off and started doing PM on it.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
1		Shipping & Handling		can	242194
4		X04242 POWERFLAME (R) ELECTR		can	242194
4		X04241 POWERFLAME (L) ELECTR		can	242194

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
1154 Shawn Shelton	2.50		1		3.50					

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative