

Date: 7/22/2024

Region: 4C  
FAC ID: WV046

CSS No.: 98184  
Maximo WO No.: 16136

Asset #: NA

Priority: Routine



**Original Work Request:**

We have 2 exterior fire extinguisher boxes that have become damaged by the sun and no longer hold the extinguishers.

**Description of Repairs Needed:**

Labor and material to a.) replace (2) exterior fire extinguisher boxes. Clean up area and properly dispose of debris generated at job site.

**Labor**

	Labor Hrs	Labor Rate	Total
Technician	6	\$ 100.00	\$ 600.00
		\$ -	\$ -

**Material List:**

	Quantity	Cost	Total
Cato 10551-B Chief Red Surface-Mounted fire Extinguisher Cabinet	2	\$ 62.57	\$ 125.14
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**Equipment List:**

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$600.00	\$125.14	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$725.14	--	--	\$725.14

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.  
6625 Selkirk Drive, Suite A  
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.  
5285 Shawnee Road Suite 510  
Alexandria, VA 22312-2334

Date: 7/22/2024 CSS #: 98184  
FAC ID: WV046 WO #: 16136

DESCRIPTION OF WORK			
Labor and material to a.) replace (2) exterior fire extinguisher boxes. Clean up area and properly dispose of debris generated at job site.			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	6	\$100.00	\$600.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
Cato 10551-B Chief Red Surface-Mounted fire Extinguisher Cabinet	2	\$62.57	\$125.14
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$600.00
	MATERIAL TOTAL		\$125.14
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$725.14

Accepted By: \_\_\_\_\_

Date: \_\_\_\_\_