

Date: 7/29/2024

Region: 4C
FAC ID: WV046

CSS No.: 98191
Maximo WO No.: 16153

Asset #: NA

Priority: Routine



Original Work Request:

The hot water pump on the glycol loop in the BMA is leaking and needs new seal.

Description of Repairs Needed:

Labor and material to a.) replace (1) 1600-868 Ceramic CRP Seal kit, b.) clean area and properly dispose of all spent materials at job site.

Labor	Labor Hrs	Labor Rate	Total
Technician	6	\$ 100.00	\$ 600.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
1600-868 CRP Seal Kit Ceramic	1	\$ 198.74	\$ 198.74
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$600.00	\$198.74	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$798.74	--	--	\$798.74

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selknick Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 7/29/2024
FAC ID: WV046

CSS #: 98191
WO #: 16153

DESCRIPTION OF WORK			
Labor and material to a.) replace (1) 1600-868 Ceramic CRP Seal kit, b.) clean area and properly dispose of all spent materials at job site.			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	6	\$100.00	\$600.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
1600-868 CRP Seal Kit Ceramic	1	\$198.74	\$198.74
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$600.00
	MATERIAL TOTAL		\$198.74
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$798.74

Accepted By: _____

Date: _____