

Date: 8/21/2024

Region: 4C
FAC ID: WV009

CSS No.: 98433
Maximo WO No.: 16156

Asset #: NA

Priority: Routine



Original Work Request:

Repair door on parts washer. Seal rusted out and water won't stay inside.

Description of Repairs Needed:

Labor and material to a.) remove old door seal, b.) provide and install (1) door seal on parts washer, c.) test for proper operation, d.) clean area and properly dispose of all debris generated at job site.

Labor	Labor Hrs	Labor Rate	Total
Technician	6	\$ 100.00	\$ 600.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
Door seal	1	\$ 123.60	\$ 123.60
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$600.00	\$123.60	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$723.60	--	--	\$723.60

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.
6625 Selkirk Drive, Suite A
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.
5285 Shawnee Road Suite 510
Alexandria, VA 22312-2334

Date: 8/21/2024 CSS #: 98433
FAC ID: WV009 WO #: 16156

DESCRIPTION OF WORK			
Labor and material to a.) remove old door seal, b.) provide and install (1) door seal on parts washer, c.) test for proper operation, d.) clean area and properly dispose of all debris generated at job site.			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	6	\$100.00	\$600.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
Door seal	1	\$123.60	\$123.60
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$600.00
	MATERIAL TOTAL		\$123.60
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$723.60

Accepted By: _____

Date: _____

