

Date: 7/30/2024

Region: 4C

CSS No.: 98589

FAC ID: WV029

Maximo WO No.: 16374

Asset #: NA

Priority: Routine



**Original Work Request:**

Repair motor pool fence - weld top guard outrigger posts along entire perimeter.

**Description of Repairs Needed:**

Labor and material to a.) repair motor pool fence by welding top guard outrigger post along entire perimeter. Approximately 103 posts with an approximate 1-inch weld on each post. Spray with cold galvanized compound on welded spots. Clean area and properly dispose of all spent materials at job site.

Labor:	Labor Hrs	Labor Rate	Total
Technician	33	\$ 150.00	\$ 4,950.00
			\$ -

Material List:	Quantity	Cost	Total
Welding Rods	1	\$ 150.00	\$ 150.00
Cold galvanized compounue	1	\$ 275.00	\$ 275.00
		\$	-
		\$	-

Equipment List:	Quantity	Cost	Total
Truck with Welding Machine	1	\$ 1,000.00	\$ 1,000.00
		\$	-
		\$	-

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 4,950.00	\$ 425.00	\$1,000.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$6,375.00	\$765.00	\$382.50	\$7,522.50

## Mill Run Enterprises, Inc

276 Casteel Road  
Bruceton Mills, WV 26525

## Estimate

Date	Estimate #
7/29/2024	140

Name / Address