

Date: 9/20/2024

Region: 4C  
FAC ID: WV029

CSS No.: 98608  
Maximo WO No.: 16597

Asset #: NA

Priority: Routine



**Original Work Request:**

Repair hole in fence by rear gate. Approximately 12" diameter.

**Description of Repairs Needed:**

Labor and material to a.) replace fencing to repair hole in fence by rear gate; approximate 12" in diameter, b.) clean up and properly dispose of all spent materials at job site.

Labor:	Labor Hrs	Labor Rate	Total
Technician	7	\$ 125.00	\$ 875.00
			\$ -

Material List:	Quantity	Cost	Total
Fencing (to match existing)	1	\$ 325.00	\$ 325.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 875.00	\$ 325.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,200.00	\$144.00	\$72.00	\$1,416.00

Mill Run Enterprises, Inc

# Estimate

276 Casteel Road  
Bruceton Mills, WV 26525

Date	Estimate #
9/17/2024	146

Name / Address
Tidewater, Inc 6625 Selnick Drive, Suite A Elkridge, MD 21075

Project			
Description	Qty	Rate	Total
Repair hole in fence by rear gate; approximate 12" in diameter. Site location: 228 Comfort Inn Road Morgantown, WV		1,200.00	1,200.00
Replacement Fencing to match existing = \$325.00 2 men; 3.5 hours each @ \$125 per hour = \$875.00			
			<b>Subtotal</b> \$1,200.00
			<b>Sales Tax (0.0%)</b> \$0.00
			<b>Total</b> \$1,200.00