

Additional Funding Request

MD002	CSS #Pending WO# 16944 Asset# NA
Description of Repairs	S&S proposes to uncover and make necessary repairs on already detected leaks. All removed dirt will be packed back in within the excavated area once leaks are repaired and deemed not leaking any longer. S&S is not responsible for fixing any leaks other than what was detected and observed by S&S for repairs. If additional leaks are found, S&S will investigate and offer a quote to repair additional leaks.
Diagnosis: Initial Work Order	Main Gas line leak located by BG&E
Diagnostic Fee	\$ 0
Additional Labor Cost to Perform Repairs	\$ 2500 S&S \$100/hr x 25
Additional Cost	\$ 0
Total Cost of Repair	\$ 2,500



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 995

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: Gas Leak
Quote No: 995
Site: MD002 Ordnance Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 04/14/2022
Valid For: 30 Day(s)

WO#: 16944

CSS Ticket Number: Pending

Problem: Main gas leak on the exterior of the building, 2" steel gas line.

S&S proposes to uncover and make necessary repairs on already detected leaks. All removed dirt will be packed back in within the excavated area once leaks are repaired and deemed not leaking any longer.

S&S is not responsible for fixing any leaks other than what was detected and observed by S&S for repairs. If additional leaks are found, S&S will investigate and offer a quote to repair additional leaks.

Service

Item	Quantity	Unit Price	Total
Labor	1	\$2,500.00	\$2,500.00
		Sub-Total ex Tax	\$2,500.00
		Tax	\$0.00
		Total inc Tax	\$2,500.00

Labor	\$2,500.00
Sub-Total ex Tax	\$2,500.00
Tax	\$0.00
Total inc Tax	\$2,500.00