

Additional Funding Request

MD019	CSS# TBD WO# 13124 Asset# NA							
Description of Repairs	SS will replace gas pressure switch							
Diagnosis: Initial Work Order	-...#3 Boiler failed needs a new gas pressure switch							
Diagnostic Fee	\$ 0							
Additional Labor Cost to Perform Repairs	\$ 600 Labor \$100/hr x 6							
Additional Material Cost to Perform Repairs	\$ 100.80 <table border="1"><tr><td>Gas pressure switch</td><td>1</td><td>100.80</td><td>100.80</td></tr></table>				Gas pressure switch	1	100.80	100.80
Gas pressure switch	1	100.80	100.80					
Total Cost of Repair	\$ 450.80 (700.80 less (\$250.00) CM Credit)							



S&S MECHANICAL

S&S Mechanical
4845 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 415

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 13124
Quote No: 415
Site: MD019 Greenspring Avenue
Site Contact:
Salesperson: Molly King
Created Date: 10/22/2020
Valid For: 30 Day(s)


MD19
13124
SOW: #3 Boiler failed needs a new gas pressure switch

Service

Item	Quantity	Unit Price	Total
Gas pressure switch	1.00	\$100.80	\$100.80
HVAC Labor Rate	6	\$100.00	\$600.00
Sub-Total ex Tax			\$700.80
Tax			\$0.00
Total inc Tax			\$700.80

Labor	\$600.00
Materials	\$100.80
Sub-Total ex Tax	\$700.80
Tax	\$0.00
Total inc Tax	\$700.80

TOTAL	\$89.04
--------------	----------------



3-21 in wc
Pmax=5.0 psi

C6097B
1028ω