



Date: 4/25/2023

Region: 4A
FAC ID: PA118

CSS No.: 91459
Maximo Work Order No.: 11802

Asset #: NA

Original Work Request:

Repair wall mounted LED light fixture in the AMSA high bay wall light is strobing.

Description of Repairs Needed:

Labor and material to a.) Change 4 LED Light Fixtures in AMSA High Bay

Material List:

(1) LED Wall Lights model: E-APR19A-T340B (19000L 4000
UL MED BZ) model: E-DI-FIXEDMNT (APR DIRECT ARM
MOUNT) -
(3) LED Ceiling Lights
model: HBC-4200U-408-BK (Round LED High Bay Light)

Equipment List:

Lift (30-35' height)

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
8	\$1,035.26	\$1,580.51	\$2,615.77