

Date: 4/18/2024

Region: 4A

FAC ID: NY126

CSS No.: 97647

Maximo WO No.: 15589

Asset #: NA

Priority: Urgent



Original Work Request:

Inspect Backflow devices located in hotbox.

Description of Repairs Needed:

Labor and material to a.) to perform inspection of (3) backflow (1-3 inch S/N 193781, 1-5/8 inch S/N 39843, and 1-10 inch S/N ME-0052)

Labor:	Labor Hrs	Labor Rate	Total
Technician	3	\$ 100.00	\$ 300.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
		\$ -	\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 300.00	\$ -	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$300.00	\$36.00	\$18.00	\$354.00

From: [Kyle Lupo](#)
To: [Julie Pape](#)
Subject: [EXTERNAL]Backflows- 49 Jetview Drive Building 17101
Date: Thursday, April 18, 2024 11:36:16 AM
Attachments: [image001.png](#)

CAUTION: External email, DO NOT click on any links/attachments unless you recognize the sender and know the content is safe

Good morning.

The backflow inspection for 49 Jetview Drive Building 17101 are \$100.00 each.
There are three backflow. The total to perform would be **\$300.00**.

Thank you,

Kyle Lupo | Inspections Account Manager | **Davis-Ulmer Fire Protection**
300 Metro Park | Rochester, NY | 14623
Mobile: 585-895-3335
Office: [585-546-3670](tel:585-546-3670)

Service Simplified

Want to make things Simple? Ask us how you can bundle your services and **SAVE** today.



DAVIS-ULMER
FIRE PROTECTION
POWERED BY API Group