

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA033 Date of Visit: 1/14/25

Contractor Personnel on Site:

1. Aaron Skeens 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO17659 Exhaust fan Asset #3531 not working.


Service Calls – Service Call Number and Description

1. CSS# 2966449 Women's restroom Exhaust fan is not working.
2. CSS# Motor is bad and needs replaced. Exhaust fan cost \$428.98
3. CSS# Fire stop caulk cost \$14.98. Total cost is \$443.96 labor (1) hours
-AS

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Aaron Skeens Date: 1/14/25


Signed: 

To be signed by Facility Manager:



By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.
This is NOT a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: James Ware Date: 1/14/25

Signed: 

E-Mail: _____



Centrifugal Downblast Roof Exhaust Fan: Direct Drive, Includes Drive Pack, 8 in Wheel, 203 cfm, 1

Item 160527 Mfr. Model 160527



Web Price \$428.98 / each
This item requires special shipping, additional charges may apply.

—Qty

Ship Pickup

Expected to arrive Tue, Jan 28.

Ship to 24740 | [Change](#)

Shipping Weight: 17.4 lbs

Ship Availability Terms

[Add to List](#)

3M Firestop Intumescent Caulk CP 25WB+ to 0.027-in H Firestop Caulk/Sealant

★★★★☆ 4.4 ✓ 304

Manufacturer Color/Finish: Red



[View All Product Options](#)

\$14.98

Pickup Delivery
at Nearest of [Fort Collins, CO](#) (46.7 mi.) [Get it tomorrow](#)

[Add To List](#)

[Add to Cart](#)

[View Full Details](#)