

**PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST**  
**SUMP PUMP**

SITE AND BLDG #: DE007 B-4

MECHANIC  
SIGNATURE: 

DATE: 07/19/22

LOCATION/RM #: WO# 18442 ASSET # OY4-192 START TIME: 0900 FINISH TIME: 1630

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
<b>SPECIAL INSTRUCTIONS</b>				
1	Follow lock out/tag out procedures at all times. De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work.	/	/	
2	Excessive sediment and debris, not removed by flushing the pit should be handled on a project basis, and not considered under this standard.	/	/	
<b>TO BE PERFORMED AT EACH INSPECTION SERVICE</b>				
1	Remove cover plates and flush pit.	/	/	
2	Inspect check valve.	/	/	
3	Inspect interior of pit for cracks.	/	/	
4	Inspect cover plate is in place	/	/	
5	Insuure the unit is operating properly, report any deficiencies	/	/	
6	Clean up work area and remove all debris.	/	/	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed discription of the deficiency.

To be perfromed by: General Maintenance Worker

**Additional Notes:**