

## Additional Funding Request

<b>DE007</b>	<b>CSS# 31235 WO# 14521</b>				
Description of Repairs	Labor and materials to replace 36 linear fluorescent bulbs.				
Diagnosis: Initial Work Order	There are multiple lights throughout the center that are not working. I am unsure if the cause is the bulbs or the ballasts. It is not the timers. The locations are the 1st floor men's locker room, the stairwell closest to the main entrance and the common area in 216.				
Diagnostic Fee	\$ 160  Labor \$80/hr x 2				
Additional Labor Cost to Perform Repairs	\$ 960  Labor \$80/hr x 12				
Additional Material Cost to Perform Repairs	\$142.20 <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Linear Flourescent Bulbs</td> <td>36</td> <td>3.95</td> <td>142.20</td> </tr> </table>	Linear Flourescent Bulbs	36	3.95	142.20
Linear Flourescent Bulbs	36	3.95	142.20		
Total Cost of Repair	\$ 1,262.20				

# WORK ESTIMATE

 CSS #: 

 Work Order #: 

 Emergency 

 Urgent 

 Routine 

 X 

Company Name:	Tidewater, Inc.		Facility ID:	DE007	
Contractor POC:	Adam Colopy				
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)		
E-Mail Address:	adam.colopy@tideh2o.net				
Assigned Technician(s):	John Brown				

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace 36 linear fluorescent bulbs.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Linear Flourescent Bulbs	36	\$3.95		\$142.20
Labor			12	\$960.00
<b>SUB-TOTAL COSTS:</b>		<b>Materials Total</b>	<b>\$142.20</b>	<b>Labor</b> <b>\$1,120.00</b>
		<b>TOTAL</b>		<b>\$1,262.20</b>

## My Products

## Reference Information

### GE CURRENT

Linear Fluorescent Bulb, T8,  
Medium Bi-Pin (G13), Lumens  
3,000 lm, 4, 100 K Color

Item #4P16



36  
QTY

Your Price

\$313.00



2

Home

Search

Help

Feedback

Cart

Logout



