

Additional Funding Request

Submitted: 10/16/20

DE007 – Boiler #1, gas regulator	CSS #27069 WO#12918												
Description of Repairs	Boiler #1-Gas regulator needs to be replaced -Found during boiler PM												
Original SC Investigative Diagnosis	NA												
Diagnosis: Initial Work Order	S&S proposes to remove and replace gas regulator for Boiler # 1.												
Explanation of Additional Costs for Repairs – CM credit	(250.00)												
Additional Material Cost to Perform Repairs	<p>Materials: \$164.40</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="padding: 2px;">Gas regulator/2-30-000105</td> <td style="padding: 2px;">1</td> <td style="padding: 2px;">\$164.40</td> <td style="padding: 2px;">\$164.40</td> </tr> <tr> <td style="padding: 2px;"> </td> <td style="padding: 2px;"> </td> <td style="padding: 2px;"> </td> <td style="padding: 2px;"> </td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Gas regulator/2-30-000105	1	\$164.40	\$164.40				
ITEM	QUANTITY	UNIT PRICE	TOTAL										
Gas regulator/2-30-000105	1	\$164.40	\$164.40										
Additional Labor Cost to Perform Repairs	<p>Labor: \$900.00</p> <p>HVAC Labor /9 hours/Rate \$100.00 per hour = \$900.00</p>												
Total Cost of Repair	\$814.40												