

Tina Lee

From: Richard Hicks
Sent: Tuesday, July 27, 2021 10:24 AM
To: Grenier, Scott Anthony CIV USARMY 99 RD (USA); Williams-Taylor, Angela W CTR USARMY 99 RD (USA); Tina Lee
Cc: Devlin, Thomas J CIV USARMY CENAP (USA)
Subject: VA048 Parts washer Power jet® Model 2846

Hi Scott ,

Here's the link to the parts washer replacement Model#2846. We are recommending replacement due to age 2011 and see below what we discovered .

Scott can I Close out CSS# 25954 WO# 14141 ? Our scope of work has been completed

| | | |
|-------|--|-----|
| 14141 | Additional work needed Parts Washer at the AMSA shop not working properly. | 99R |
|-------|--|-----|

- The filters have been removed from parts washer
- Sediment has built up in sump around heaters possibly causing heater failure
- The surface oil has not been drained off as recommended causing Sediment build up
- New unit costs \$5K plus install , environmental removal of old fluids , and removal and disposal of old parts washer .
- Possibly you can do this through one of your contracts , ACC-NJ

[Automotive & Industrial Parts Washers Price List | Powerjet® EMC \(equipmentmanufacturing.com\)](http://Automotive & Industrial Parts Washers Price List | Powerjet® EMC (equipmentmanufacturing.com))

Thanks ,
Rick

Rick Hicks
PM / 99TH -Region 5
5285 Shawnee Road
Suite #510
Alexandria , VA 22312
703-738-5301
Richard.Hicks@cmimgmt.com