

Date: 1/15/2025

Region: 4C

CSS No.: 2935120

FAC ID: WV010

Maximo WO No.: 17094

Asset #: NA

Priority: Urgent



Original Work Request:

Repair/adjust bay door 6 in Motor Pool. Will not open.

Description of Repairs Needed:

Labor and material to a.) Diagnose and repair if possible Bay Door 6 in the Motor Pool. If any additional repairs are needed a separate estimate will be submitted.

Labor:

	Labor Hrs	Labor Rate	Total
Technician (2 x 12 hrs)	24	\$ 95.00	\$ 2,280.00
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 2,280.00	\$ -	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,280.00	\$273.60	\$136.80	\$2,690.40

LoCurrent Systems, LLC

3522 County Highway 11
 Cooperstown, NY 13326
 (607)293-7300
 locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
 6625- A Selnick Drive
 Elkridge, MD 21075

ESTIMATE # 2626**DATE** 01/14/2025**P.O. NUMBER**

Bridgeport,WV Diag/Rep Bay Door

	ACTIVITY	QTY	AMOUNT
01/14/2025	Services Bridgeport, WV010 Clarksburg USARC Diagnose and Repair if Possible Bay Door 6 (FEMS 2935120)	1	2,280.00

Dear Ms. Pape,

As per your request, LoCurrent Systems is pleased to provide you a quotation to Diagnose and Repair if possible Bay Door 6 in the Motor Pool at the Clarksburg, USARC in Bridgeport, WV.

Description of Issues: "Will Not Open"

Cost Breakdown:

(2) Men 12 Hours @
 \$95/hr.....\$2,280.00

Grand
 Total.....\$2,280.00

The Total Cost for the above mentioned work is \$2,280.00.

If acceptable, please do not hesitate to contact us so we may schedule for work to be completed.

ACTIVITY	QTY	AMOUNT
Thank you for thinking of LoCurrent Systems.		
Sincerely,		
Antonietta LoRusso		

	TOTAL	\$2,280.00
--	-------	-------------------

Accepted By

Accepted Date