

Date: 12/10/2025

Region: 4C

FEMS No.: 2965936

FAC ID: WV031

Maximo WO No.: 17638

Asset #: NA

Priority: Routine



Original Work Request:

Repair bad contactor. the contactor for exterior lights on the VMS is stuck because of moisture intrusion and corrosion and not working this causes a security issue at night.

Description of Repairs Needed:

Labor and material to inspect VMS and locate bad contactor controlling exterior lights. Order correct replacement contactor and make return trip to install. Reconnect wiring and test exterior lighting.

Labor:

	Labor Hrs	Labor Rate	Total
Technicians	9	\$ 100.00	\$ 900.00
		\$	-

Material List:

	Quantity	Cost	Total
Contactor	1	\$ 315.00	\$ 315.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 900.00	\$ 315.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,215.00	\$145.80	\$72.90	\$1,433.70



CMI
1370 N. State St.
New Martinsville, WV 26155

RE: Lighting Contactors

Date
12/9/25

Work Description:

**Replace three 40 amp, two pole contactors that are controlling exterior lights.
Reset controls and test lights.**

Labor = \$ 900.00

Material = \$ 315.00

Total Cost = \$ 1,215.00

Expiration Date:

Terms:

Authorized Signature: _____ Date: _____

Please sign and return authorized quote to office below

523 Slack Street
Charleston, WV 25301
Fax: 304-346-5502

www.bossieelectric.com