

Date: 3/14/2025

Region: 4C

FEMS No.: 3030873

FAC ID: WV010

Maximo WO No.: 17936

Asset #: NA

Priority: Routine



**Original Work Request:**

Repair softball sized hole in fence - Motor Pool. Physical Security issue.

**Description of Repairs Needed:**

Labor and material to a.) repair softball sized hole in fence - motor pool, b.) replace section of fencing to match existing.

**Labor:**

	Labor Hrs	Labor Rate	Total
Technician (2 x 3.75 hours)	7.5	\$ 150.00	\$ 1,125.00
			\$ -

**Material List:**

	Quantity	Cost	Total
replacement fencing to match existing	1	\$ 375.00	\$ 375.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**Equipment List:**

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 1,125.00	\$ 375.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,500.00	\$180.00	\$90.00	\$1,770.00

Mill Run Enterprises, Inc

276 Casteel Road  
Bruceton Mills, WV 26525

# Estimate

Date	Estimate #
3/14/2025	165

Name / Address
Tidewater, Inc 6625 Selnick Drive, Suite A Elkridge, MD 21075

		Project	
Description	Qty	Rate	Total
Repair softball sized hole in fence - motor pool. Site location: WV010 Clarksburg USARC/OMS 77 Meadowbrook Road Bridgeport, WV		1,500.00	1,500.00
Replacement Fencing to match existing: = \$375.00 2 men; 3.75 hours each @ \$150.00 per hour = 1125.00			
		<b>Subtotal</b>	\$1,500.00
		<b>Sales Tax (0.0%)</b>	\$0.00
		<b>Total</b>	\$1,500.00