

Date: 4/10/2025

Region: 4A

FEMS No.: 3071346

FAC ID: NY070

Maximo WO No.: 18501

Asset #: NA

Priority: Routine



**Original Work Request:**

Replace 4 missing ceiling tile in room 122. Replace 4 missing ceiling tile in room 122. Ceiling tile were damaged due to a roof leak. The leak has now stopped, so the tile should be replaced.

**Description of Repairs Needed:**

Labor and material to a) replace stained ceiling tiles in room 122 b) clean up and properly dispose of all spent materials at job site.

**Labor:**

	Labor Hrs	Labor Rate	Total
Technician	4	\$ 100.00	\$ 400.00
			\$ -

**Material List:**

	Quantity	Cost	Total
Materials	1	\$ 22.00	\$ 22.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**Equipment List:**

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 400.00	\$ 22.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$422.00	\$50.64	\$25.32	\$497.96

**HUNOLD CONTRACTING INC.**  
72 PENDERGAST ROAD  
PHOENIX, NY 13135  
Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape  
6625 Selmick Dr., Suite A  
Elkridge, MD 21075

**ESTIMATE**  
**4/9/25**

<b>Quantity</b>	<b>Description</b>	<b>Amount</b>
1	FEMS 3071346, WO 18501, NY070 Webster, NY  Replace stained ceiling tiles in room 122.  Material: (\$22)  Labor: (4 hours @ \$100/ hr.) = \$400	<b>422.00</b>
		<b>Sub total</b> <b>422.00</b>
		<b>Sales Tax</b> <b>N/A</b>
		<b>Total</b> <b>422.00</b>

Signature\_\_\_\_\_ Date\_\_\_\_\_

Signature\_\_\_\_\_ Date\_\_\_\_\_