

Date: 5/6/2025



Region: 4A

FEMS No.: 3071355

FAC ID: NY030

Maximo WO No.: 18764

Asset #: NA

Priority: Routine

**Original Work Request:**

Replace 6 light fixtures in basement army side of facility. 2 fixtures have bad ballast and the other 4 have bulbs that are starting to dim. Current fixtures are fluorescent and should be replaced with LED fixtures.

**Description of Repairs Needed:**

Labor and material to c) remove old fixtures, b) supply & replace (6) Lithonia model# FML4W fixtures in the basement on the army side of the training center, c) test for proper operation, d) clean up and properly dispose of all spent materials.

Labor:	Labor Hrs	Labor Rate	Total
Service Technician	10	\$ 100.00	\$ 1,000.00
			\$ -

Material List:	Quantity	Cost	Total
Lithonia model # FML4W	6	\$ 86.00	\$ 516.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

NA
----

**Estimate Summary:**

Labor	Material	Equipment
\$ 1,000.00	\$ 516.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,516.00	\$181.92	\$90.96	\$1,788.88

**HUNOLD CONTRACTING INC.**

72 PENDERGAST ROAD

PHOENIX, NY 13135

Cell # 315-247-5898

Customer:

Tidewater Attn: Adam Colopy

6625 Selmick Dr., Suite A

Elkridge, MD 21075

**ESTIMATE****5/1/25**

<b>Quantity</b>	<b>Description</b>	<b>Amount</b>
1	FEMS 3071355, NY030 Horseheads, NY WO18764  Replace 6 lights in the basement on the army side of the training center. Remove and dispose of old fixtures.  Material Total: (\$516) 6- Lithonia model# FML4W (\$86/ ea.)  Labor Total: (10 hours @ \$100/ hr.) =\$1000	<b>1516.00</b>
<b>Sub total</b>		<b>1516.00</b>
<b>Sales Tax</b>		<b>N/A</b>
<b>Total</b>		<b>1516.00</b>

**Signature**\_\_\_\_\_ **Date**\_\_\_\_\_**Signature**\_\_\_\_\_ **Date**\_\_\_\_\_